



DEPARTMENT OF THE NAVY
HEADQUARTERS UNITED STATES MARINE CORPS
3000 MARINE CORPS PENTAGON
WASHINGTON, D.C. 20350-3000

NAVMC 4790.02

C 465

15 JUN 2012

NAVMC 4790.02

From: Commandant of the Marine Corps
To: Distribution List

Subj: RQ-7B SHADOW UNMANNED AIRCRAFT SYSTEMS MAINTENANCE TRAINING AND READINESS MANUAL (SHORT TITLE: RQ-7B UAS MAINTENANCE T&R MANUAL)

Ref: (a) NAVMC 4790.01

Encl: (1) RQ-7B Shadow Unmanned Aircraft Systems (UAS) Maintenance T&R Manual

1. Purpose. In accordance with the reference and enclosure, publish standards and regulations regarding the training of RQ-7B Shadow UAS maintenance.

2. Scope. Highlights of major training and readiness planning considerations included in this new RQ-7B Shadow UAS Maintenance T&R Manual are as follows:

a. Establishes unit assessment and individual evaluation programs.

b. Establishes RQ-7B Shadow UAS maintenance billets and defines required training for each.

c. Establishes training requirements for attaining, maintaining and regaining currency, designations and qualifications.

3. Information. Recommended changes to this Manual are invited, and may be submitted via the Maintenance Training Syllabus Sponsor (MTSS) and the appropriate chain of command to: Commanding General (CG), Training and Education Command (TECOM), Marine Air Ground Task Force Training and Education (MAGTF T&E) Standards Division, Aviation Standards Branch (ASB) using standard Naval correspondence or the Automated Message Handling System (AMHS) plain language address: CG TECOM ATD.


4. Command. This Manual is applicable to the Marine Corps Total Force.

5. Certification. Reviewed and approved this date.

R. C. FOX
By direction

DISTRIBUTION: PCN 10047001100

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.



CHAPTER 1
RQ-7B Shadow Unmanned Aircraft System
Maintenance Department Training and Readiness

Table of Contents

Paragraph	Page
1.0 Maintenance Department Core Competency.	1-2
1.1 Mission Statement	1-2
1.2 Maintenance Department Mission.	1-2
1.3 Table of Organization (T/O)	1-2
1.4 RQ-7B Community System Skill Core Model Minimum Requirement (CMMR) Matrix	1-2
1.5 RQ-7B Community Maintenance Leadership Core Model Minimum Requirement (CMMR)	1-4

List of Tables

- Table 1-01. RQ-7B Table of Organization (T/O) Information
- Table 1-02. RQ-7B Community System Skills Proficiency CMMR Matrix (Squadron)
- Table 1-03. RQ-7B Community System Skills Proficiency CMMR Matrix (Squadron Minus)
- Table 1-04. RQ-7B Community System Skills Proficiency CMMR Matrix (Squadron Detachment)
- Table 1-05. RQ-7B Community Maintenance Leadership CMMR (Squadron)
- Table 1-06. RQ-7B Community Maintenance Leadership CMMR (Squadron Minus)
- Table 1-07. RQ-7B Community Maintenance Leadership CMMR (Squadron Detachment)

1.0 MAINTENANCE DEPARTMENT CORE COMPETENCY. Marine aviation plays a crucial role in the Marine Air Ground Task Force's (MAGTF's) ability to conduct maneuver warfare. The ultimate goal of Marine aviation is to attain the highest possible combat readiness to support expeditionary maneuver warfare while preserving and conserving our Marines and equipment. Embedded within our combat readiness is the ability to rapidly, effectively, and efficiently deploy on short notice, and to quickly and effectively plan for crises and/or contingency operations, thereby ensuring Marine aviation remains ready for combat when and where the need arises. The Aircraft Maintenance Training and Readiness Program (AMTRP) represents the collaborative effort of Marine aircraft maintenance Subject Matter Experts (SMEs) to maximize efficient and effective aircraft system maintenance. These standards describe and define maintenance department/division capabilities and requirements necessary to maintain like-unit proficiency in system skills, qualifications, designations, and licensing. Training tasks are based on specific requirements and performance standards that ensure personnel maintain a common base of training and depth of capabilities. The T&R is a building block approach to ensure personnel are trained and remain ready, relevant, and capable of supporting the MAGTF Commander.

1.1 MISSION STATEMENT. Conduct day and night unmanned aerial Reconnaissance, Surveillance and Target Acquisition (RSTA) in support of the Marine Air-Ground Task Force (MAGTF).

1.2 MAINTENANCE DEPARTMENT MISSION. The Maintenance Department supports the overall unit mission by providing Ready Basic Aircraft (RBA)/Ready For Tasking (RFT) aircraft to support operations in accordance with higher headquarters tasking.

1.3 TABLE OF ORGANIZATION (T/O). The following RQ-7B active unit forces are authorized as annotated in the following tables:

Table 1-01 RQ-7B Table of Organization (T/O) information.

MOS	6314
VMU-1 [3 Systems]	43
VMU-2 [3 Systems]	43
VMU-3 [3 Systems]	43
VMU-4 [3 Systems]	44

1.4 RQ-7B COMMUNITY SYSTEM SKILL CORE MODEL MINIMUM REQUIREMENT (CMMR) MATRIX. Maintenance department training and readiness requires SME-determined numbers of system skill proficient Marines in order to sustain unit operations. The following tables provide a list of all systems by MOS for the RQ-7B Community System Skill CMMR Matrix.

Table 1-02 RQ-7B Community System Skills Proficiency CMMR Matrix
(Squadron)

RQ-7B Maintenance System Skill Areas	System	Repairer
		6314
"C" School	CSCH	31
Inspections System	INSP	31
Corrosion	CORS	31
Unmanned Air Vehicle	UAVS	31
Engine/Propulsion System	ENGS	31
Fuel System	FUEL	31
Launcher System	LAUN	31
Aircraft Avionics Systems	AVIS	31
Plug In Optronics Payload	POPS	31
Ground Control Station/Ground Data Terminal	GCSS	31
Portable Ground Control/Data Terminal	PGCS	31
Tactical Automated Landing System	TALS	31
UAS Emplacement/Displacement	EMPL	31
Enhanced Logbook Automation System	ELAS	31

Table 1-03 RQ-7B Community System Skill Proficiency CMMR Matrix
(Squadron Minus)

RQ-7B Maintenance System Skill Areas	System	Repairer
		6314
"C" School	CSCH	21
Inspections System	INSP	21
Corrosion	CORS	21
Unmanned Air Vehicle	UAVS	21
Engine/Propulsion System	ENGS	21
Fuel System	FUEL	21
Launcher System	LAUN	21
Aircraft Avionics Systems	AVIS	21
Plug In Optronics Payload	POPS	21
Ground Control Station/Ground Data Terminal	GCSS	21
Portable Ground Control/Data Terminal	PGCS	21
Tactical Automated Landing System	TALS	21
UAS Emplacement/Displacement	EMPL	21
Enhanced Logbook Automation System	ELAS	21

**Table 1-04 RQ-7B Community System Skill Proficiency CMMR Matrix
(Squadron Detachment)**

RQ-7B Maintenance System Skill Areas	System	Repairer
"C" School	CSCH	10
Inspections System	INSP	10
Corrosion	CORS	10
Unmanned Air Vehicle	UAVS	10
Engine/Propulsion System	ENGS	10
Fuel System	FUEL	10
Launcher System	LAUN	10
Aircraft Avionics Systems	AVIS	10
Plug In Optronics Payload	POPS	10
Ground Control Station/Ground Data Terminal	GCSS	10
Portable Ground Control/Data Terminal	PGCS	10
Tactical Automated Landing System	TALS	10
UAS Emplacement/Displacement	EMPL	10
Enhanced Logbook Automation System	ELAS	10

1.5 RQ-7B COMMUNITY MAINTENANCE LEADERSHIP CMMR. The following tables provide the minimum requirement of maintenance leadership to sustain unit operations for the squadron, squadron minus, and detachment.

Table 1-05 RQ-7B Community Maintenance Leadership CMMR (Squadron)

RQ-7B Maintenance Leadership	Repairer	Q/A	M/C
	6314	6314	6314
Quality Assurance Representative (QAR)		6	
Collateral Duty QAR (CDQAR)			
Collateral Duty Inspector (CDI)	6		
Safe For Flight			6
Plane Captain	6		

Table 1-06 RQ-7B Community Maintenance Leadership CMMR (Squadron Minus)

RQ-7B Maintenance Leadership	Repairer	Q/A	M/C
	6314	6314	6314
Quality Assurance Representative (QAR)		4	
Collateral Duty QAR (CDQAR)	4		
Collateral Duty Inspector (CDI)	4		
Safe For Flight			4
Plane Captain	4		

Table 1-07 RQ-7B Community Maintenance Leadership CMMR (Squadron Detachment)

RQ-7B Maintenance Leadership	Repairer	Q/A	M/C
	6314	6314	6314
Quality Assurance Representative (QAR)		2	
Collateral Duty QAR (CDQAR)	2		
Collateral Duty Inspector (CDI)	2		
Safe For Flight			2
Plane Captain	2		

CHAPTER 2

RQ-7B Shadow Unmanned Aircraft System Repairer
Training And Readiness Requirements

Table of Contents

Paragraph	Page
2.0 Purpose	2-3
2.1 Maintenance Systems	2-3
2.1.1 "C" School.	2-3
2.1.2 Inspections System (INSP)	2-19
2.1.3 Corrosion Control System (CORS)	2-49
2.1.4 Unmanned Aircraft System (UAVS)	2-53
2.1.5 Engine System (ENGS).	2-73
2.1.6 Fuel System (FUEL).	2-86
2.1.7 Launcher System (LAUN).	2-90
2.1.8 Aircraft Avionics System (AVIS)	2-101
2.1.9 Plug In Optronic Payload System (POPS).	2-128
2.1.10 Ground Control Station/Ground Data Terminal System (GCS/GDT). . .	2-134
2.1.11 Portable Ground Control Station/Portable Ground Data Terminal System (PGCS/PGDT).	2-212
2.1.12 Tactical Automated Landing System (TALS).	2-227
2.1.13 UAS EMPLACEMENT/DISPLACEMENT SYSTEM (EMPL).	2-240
2.1.14 Enhanced Logbook Automated System (ELAS).	2-258
2.2.5 Foreign Object Damage Prevention Program.	2-294
2.2.6 Fuel Surveillance Program	2-310
2.2.7 Hazardous Material Control Program.	2-328
2.2.8 Hydraulic Contamination Program	2-340
2.2.9 Maintenance In-Service Training Program	2-340
2.2.10 Metrology/Calibration Program	2-350
2.2.11 Naval Aviation Discrepancy Reporting Program.	2-360
2.2.12 Oil Consumption Program	2-371
2.2.13 Plane Captain Qualification Program	2-384
2.2.15 Quality Assurance Audit Program	2-404
2.2.16 Support Equipment Training and Licensing Program.	2-410
2.2.18 Technical Directive Compliance Program.	2-410
2.2.19 Tool Control Program.	2-424
2.2.20 Tire and Wheel Program.	2-435
2.3 Non-NAMPSOP Programs.	2-435

NAVMC 4790.02	
15 Jun 12	
2.3.1 Aircraft Confined Space Program	2-436
2.3.2 APU Taxi Turn Up Program.	2-436
2.3.3 Battery Safety Program.	2-437
2.3.4 Centralized Technical Publications Library Program.	2-448
2.3.5 Laser Hazard Control Program.	2-463
2.3.6 Maintenance Department/Division Safety Program.	2-477
2.3.7 Support Equipment Misuse and Abuse Program.	2-489
2.3.8 Corrosion Prevention and Control Program.	2-490
2.3.9 Electrostatic Discharge Program	2-505

2.0 Purpose. To provide the required System Skill Proficiency (SSP), Naval Aviation Maintenance Program (NAMP), and Non-Naval Aviation Maintenance Standard Operating Procedures (Non-NAMPSOP) Program requirements for MOS 6314 personnel to achieve the needed qualifications, designations, and licenses to support the unit mission.

2.1 Maintenance Systems. The maintenance system tasks within the T&R are to train an individual with all MOS requirements to attain and sustain MOS proficiency. The T&R contains all training evolutions to include "C" school tasks and all SME developed maintenance tasks that guide an individual to all qualifications and designations within that respective MOS.

2.1.1 "C" School Curriculum (CSCH). The "C" School Tasks provide the curriculum taught for an MOS at the CNATT MARUNIT.

Table 2-01. Maintenance System "C School"

Maintenance System "C School" System					
INDOC	BASIC	INTERMEDIATE	ADVANCED	MGMT	QDL
1001-1033					

NOTE
For task header description see Appendix A

CSCH-1001-15EC01L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Identify the Shadow 200 Unmanned Aircraft System major components.

Requirement. N/A

Performance Standard. With supervision, given a classroom environment, computer, maintenance publications, references, and student handout, identify the Shadow 200 Unmanned Aircraft System major components.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. N/A

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1002-15EC02L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Emplace and displace the electrical power equipment.

Requirement. N/A

15 Jun 12

Performance Standard. With supervision, given a classroom environment, maintenance instructional facility, computer, Ground Control Station (GCS), Ground Data Terminal (GDT), Launcher (LAU), maintenance section multifunctional, personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the Shadow 200 System electrical power equipment.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. N/A

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1003-15EC03L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Emplace and displace the Ground Control Station (GCS).

Requirement. Perform the following:

1. Emplace
2. Displace
3. Perform preventive maintenance checks
4. Power up Ground Control Station (GCS)
5. Power down Ground Control Station (GCS)

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, unsurfaced fixed wing runway, computer, Ground Control Station (GCS), personal protective equipment, maintenance publications and references, forms and records, and student handout, emplace/displace Ground Control Station (GCS).

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1004-15EC04L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Emplace and displace the Ground Data Terminal (GDT).

Requirement. Perform the following:

1. Emplace

2. Displace
3. Perform preventative maintenance checks

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, unsurfaced fixed wing runway, computer, Ground Control Station (GCS), Ground Data Terminal (GDT), personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the Shadow Ground Data Terminal (GDT).

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. N/A

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1005-15EC05L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Emplace and displace the Portable Ground Control Station (PGCS) and Portable Ground Data Terminal (PGDT).

Requirement. Perform the following:

1. Emplace
2. Displace
3. Perform preventative maintenance checks on the Portable Ground Control Station (PGCS)
4. Perform preventive maintenance checks on the Portable Ground Data Terminal (PGDT)
5. Power up the PGCS and PGDT
6. Power down the PGCS and PGDT

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, unsurfaced fixed wing runway, computer, Air Vehicle Transport, Portable Ground Control Station, Portable Ground Data Terminal, Maintenance Section Multifunctional, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, deploy the Shadow Portable Ground Control Station and Portable Ground Data Terminal.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1006-15EC06L/001	[N/A]	N/A	N/A	B	N/A	C	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Emplace and Displace Launcher

Requirement

1. Emplace
2. Displace

Performance Standard. With supervision, given a classroom environment, pad (hard stand), unsurfaced fixed wing runway, computer, launch and recovery trailer, air vehicle transport, personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the launcher.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1007-15EC07L/001	[N/A]	N/A	N/A	B	N/A	C	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Emplace and displace the Tactical Automatic Landing System (TALS)

Requirement. Perform the following:

1. Emplace
2. Displace
3. Perform preventative maintenance checks
4. Power up the TALS.
5. Power down the TALS

Performance Standard. With supervision, given a classroom environment, unsurfaced fixed wing runway, computer, tactical automatic landing system, portable ground control station, air vehicle transport, global positioning satellite receiver, maintenance section multifunctional, personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the shadow tactical automatic landing system.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1008-15EC08L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Emplace and displace the Shadow Unmanned Aircraft and Air Vehicle Transport.

Requirement. Perform the following:

1. Emplace the Air Vehicle Transport
2. Assemble the Shadow Unmanned Aircraft
3. Disassemble the Shadow Unmanned Aircraft
4. Displace the Air Vehicle Transport

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, unsurfaced fixed wing runway computer, shadow unmanned aircraft, air vehicle transport, personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the shadow unmanned aircraft and air vehicle transport.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1009-15EC09L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Emplace and displace the One System Remote Video Terminal (OSRVT).

Requirement. Perform the following:

1. Emplace the One System Remote Video Terminal (OSRVT)
2. Displace the OSRVT
3. Perform preventative maintenance checks on the OSRVT,
4. Power up the OSRVT
5. Power down the OSRVT

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, unsurfaced fixed wing runway computer, one system remote video terminal, maintenance section multifunctional, personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the one system remote video terminal.

Prerequisites. N/A

15 Jun 12

External Syllabus Support. N/AAcademics:References.Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1010-15EC10L/001	[N/A]	N/A	N/A	B	N/A	C	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Emplace and displace the Arresting Gear (AG).Requirement. Perform the following:

1. Emplace the Arresting Gear (AG)
2. Displace the Arresting Gear (AG)
3. Perform preventative maintenance checks on the AG
4. Perform the caliper brake pressure test and adjustment

Performance Standard. With supervision, given a classroom environment, unsurfaced fixed wing runway, launch and recovery trailer, computer, air vehicle transport, personal protective equipment, maintenance publications and references, forms and records, and student handout, deploy the shadow arresting gear with net.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References.Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1011-15EC11L/001	[N/A]	N/A	N/A	B	N/A	C	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Emplacement and displacement round robin training.Requirement. Deploy the Shadow Unmanned Aircraft System in accordance with applicable references, emplace/displace Shadow equipment, perform the daily Preventive Maintenance Checks and Services on Shadow equipment, perform power up and power down on Shadow equipment.Performance Standard. With supervision, given an unsurfaced fixed wing runway, computer, Ground Control Station, Ground Data Terminal, Portable Ground Control Station, Portable Ground Data Terminal, Launch and Recovery Trailer, Tactical Automatic Landing System, Air Vehicle Transport, Shadow Unmanned Aircraft, One System Remote Video Terminal, Global Positioning System Receiver, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, deploy the Shadow System equipment.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1012-15EC12T/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. System Emplacement Written Evaluation.

Requirement. Achieve a minimum score of 80 percent on each section to pass this evaluation.

Performance Standard. With supervision, given a classroom environment, computer, maintenance publications and references, student handouts, student notes, evaluation booklet, answer sheet and pencils, apply the skills and knowledge acquired in 15EC01L System Overview and 15EC02L Shadow System Electrical Power Equipment.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1013-15ED01L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Ground Emergency Procedures.

Requirement. Achieve a passing grade by completing all periodic bold-face examinations without error.

Performance Standard. With supervision, given a classroom environment, computer, maintenance publications and references, and student handout, react to Ground Emergencies.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. Work Center SupervisorCSCH-1014-15ED02L/001 [N/A] N/A N/A B N/A C N/A Times: 1Task. Module D; Launcher Inspections and Maintenance.Requirement. Perform the Launcher daily preventative maintenance checks and services and pre-operational checks in accordance with applicable references, locating 3 out of 3 instructor inserted faults.Performance Standard. With supervision, given a classroom environment, unsurfaced fixed wing runway, computer, Launch and Recovery Trailer, Air Vehicle Transport, Maintenance Section Multifunctional, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, prepare the launcher for flight operations.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References.Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center SupervisorCSCH-1015-15ED03L/001 [N/A] N/A N/A B N/A C N/A Times: 1Task. Module D; Shadow Aircraft Daily inspection.Requirement. Perform the Shadow Unmanned Aircraft preventative maintenance daily inspection in accordance with applicable references, locating 4 out of 5 instructor inserted faults.Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, computer, Air Vehicle Transport, Shadow Unmanned Aircraft, Maintenance Section Multifunctional, maintenance publications and references, forms and records, and student handout, perform a daily inspection on the Shadow aircraft.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References.Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center SupervisorCSCH-1016-15ED04L/001 [N/A] N/A N/A B N/A C N/A Times: 1Task. Module D; Shadow Unmanned Aircraft Fueling and De-fueling.

Requirement. Performed the Shadow Unmanned Aircraft Fuel / de-fuel procedures in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, unsurfaced fixed wing runway, computer, Air Vehicle Transport, Shadow Unmanned Aircraft, Maintenance Section Multifunctional, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, fuel and de-fuel the Shadow Unmanned Aircraft.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1017-15ED05L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module D; Shadow Unmanned Aircraft Scheduled Maintenance.

Requirement. Remove and replace the propeller and perform the 50 hour aircraft service in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Maintenance Section Multifunctional, Portable Ground Control Station, Portable Ground Data Terminal, engine trainer, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, perform Shadow Unmanned Aircraft scheduled maintenance.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1018-15ED06L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module D; Shadow Unmanned Aircraft Unscheduled Maintenance.

Requirement. Replace the Shadow Unmanned Aircraft engine in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Maintenance Section Multifunctional,

15 Jun 12

Portable Ground Control Station, Portable Ground Data Terminal, engine trainer, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, replace the Shadow Unmanned Aircraft engine.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1019-15ED07L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module D; Arresting Gear Maintenance.

Requirement. Replace the energy absorber strap and perform monthly preventative maintenance checks and services on the energy absorbers in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, aircraft maintenance facility, computer, arresting gear energy absorber, Air Vehicle Transport, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, perform Shadow Unmanned Aircraft System Arresting Gear maintenance.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1020-15ED08L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module D; Modem Programming and Magnetometer Calibration.

Requirement. Program the aircraft modems, set the video transmitter frequency, and calibrate the magnetometer in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Portable Ground Control Station, Portable Ground Data Terminal, Maintenance Section Multifunctional, maintenance publications and references, forms and records, and student handout, perform Modem Programming and Magnetometer Calibration.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1021-15ED09L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module D; Maintenance Round Robin Training.

Requirement. Complete all steps in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, unsurfaced fixed wing runway, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Launcher, Maintenance Section Multifunctional, Portable Ground Control Station, Portable Ground Data Terminal, engine trainer, arresting gear trainer, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, complete the Maintenance Round Robin Training.

1. Perform the Launcher daily Preventative Maintenance Checks and Services (PMCS) and pre-operational checks locating 3 out of 3 instructor inserted faults.
2. Perform the Shadow Unmanned Aircraft preventative maintenance daily inspection locating 4 out of 5 instructor inserted faults.
3. Perform the Shadow Unmanned Aircraft fueling procedures.
4. Replace the propeller and perform the 50 hour Shadow Unmanned Aircraft service.
5. Replace the Shadow Unmanned Aircraft engine.
6. Replace the energy absorber strap and perform the Arresting Gear monthly PMCS.
7. Program the Shadow Unmanned Aircraft modems, set the video transmitter frequency, and calibrate the magnetometer.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1022-15EE01L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module E; Shadow Unmanned Aircraft Shipping and Unpacking.

15 Jun 12

Requirement. Perform Shadow Unmanned Aircraft shipping and unpacking procedures in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, aircraft maintenance instructional facility, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Maintenance Section Multifunctional, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, perform Shadow Unmanned Aircraft shipping and unpacking procedures.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References:

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1023-15EE02L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module E; Shadow Unmanned Aircraft Launch Procedures.

Requirement. Perform all steps as the crew chief in accordance with applicable references:

1. Perform preflight checks
2. Perform engine start procedures
3. Perform launch procedures
4. Demonstrate crew coordination
5. React to an emergency.

Performance Standard. With supervision, given a classroom environment, unsurfaced fixed wing runway, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Portable Ground Control Station, Portable Ground Data Terminal, Launcher, Maintenance Section Multifunctional, Radio Set AN/PRC-148, Tactical Automatic Landing System, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, perform Shadow Unmanned Aircraft launch procedures.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References:

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1024-15EE03L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module E; Flight Operations Round Robin Training.

Requirement. Complete all steps in accordance with applicable references:

1. Perform preflight checks as the crew chief.
2. Perform engine start procedures as the crew chief.
3. Perform launch procedures as the crew chief.
4. Demonstrate crew coordination as the crew chief.
5. React to an emergency as the crew chief.
6. Perform shipping procedures of the Shadow Unmanned Aircraft.

Performance Standard. With supervision, given a classroom environment, unsurfaced fixed wing runway, computer, Shadow Unmanned Aircraft, Air Vehicle Transport, Portable Ground Control Station, Portable Ground Data Terminal, Launcher, Maintenance Section Multifunctional, Radio Set AN/PRC-148, Tactical Automatic Landing System, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, perform Shadow Unmanned Aircraft shipping/unpacking and launch procedures.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1025-15EF01L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module F; Ground Control Station Description and Operation.

Requirement. Identify the Ground Control Station components and functions in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, computer, Ground Control Station, Personal Protective Equipment, maintenance publications and references, forms and records, and student handouts, identify the Ground Control Station components and their functions.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. Work Center SupervisorCSCH-1026-15EF02L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module F; Ground Control Station/Portable Ground Control Station Screen Descriptions.

Requirement. Establish communications with the Shadow Unmanned Aircraft using the Ground Control Station/Portable Ground Control Station control panels in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, simulations center, computer, maintenance publications and references, forms and records, and student handouts, establish communications with the Shadow Unmanned Aircraft using the Ground Control Station and the Portable Ground Control Station's control panels.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center SupervisorCSCH-1027-15EF03L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module F; Shadow Unmanned Aircraft Electrical Power System and Electronic System Theory of Operation.

Requirement. Identify components of the Aircraft Electrical Power System in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, computer, maintenance publications and references, forms and records, and student handouts, identify the components of the Shadow Unmanned Aircraft Electrical Power System and Electronic System Theory of Operation.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center SupervisorCSCH-1028-15EF04L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module F; System Communications.

Requirement. Establish voice communication between the AN/PRC-148, the Portable Ground Control Station using the VRC-89, and the Ground Control Station using the VRC-92 in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, computer, Ground Control Station, Portable Ground Control Station, radio sets AN/PRC-148, VRC-89, VRC-92, Air Vehicle Transport, Personal Protective Equipment, maintenance publications and references, forms and records, and student handouts, establish voice communication between the AN/PRC-148, the Portable Ground Control Station using the VRC-89, and the Ground Control Station using the VRC-92.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1029-15EF05L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module F; System Data Link Communications.

Requirement. Identify the components, communications format, signal path and functions of the system data link in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, computer, maintenance publications and references, forms and records, and student handouts, identify the components, communications format, signal path, and functions of System Data Link.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References.

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1030-15EF06L/001 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module F; Plug-in Optronic Payload 300.

Requirement. Identified the operating principles of the Plug-in Optronic Payload 300 in accordance with applicable references.

Performance Standard. With supervision, given a classroom environment, computer, maintenance publications and references, and student handout, identify the operating principles of the Plug-in Optronic Payload 300.

15 Jun 12

Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References.Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1031-15EF07L/001	[N/A]	N/A	N/A	B	N/A	C	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Module F; Shadow Ground Systems Lab.Requirement. Perform maintenance on the Shadow Ground System Equipment in accordance with applicable references.Performance Standard. With supervision, given a classroom environment, computer, Ground Data Terminal, Tactical Automatic Landing System, Ground Control Station, Air Vehicle Transport, Maintenance Section Multifunctional, maintenance publications and references, forms and records, and student handout, perform maintenance on the Shadow Ground System Equipment.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References.Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1032-15EF08L/001	[N/A]	N/A	N/A	B	N/A	C	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Module F; Shadow System Lab.Requirement. Isolate 3 out of 4 instructor inserted faults, using logical troubleshooting, in accordance with applicable references.Performance Standard. With supervision, given a classroom environment, situations /descriptions, computer, Ground Control Station, Ground Data Terminal, Shadow Unmanned Aircraft, Personal Protective Equipment, maintenance publications and references, forms and records, and student handout, fault isolate the Shadow Unmanned Aircraft System.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References.Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-1033-15EG01L/002 [N/A] N/A N/A B N/A C N/A Times: 1

Task. Module G; Shadow Unmanned Aircraft Launch Procedures.

Requirement. Completed all steps in accordance with applicable references:

1. Perform maintenance and inspections on the Shadow Unmanned Aircraft System equipment.
2. Perform troubleshooting and repair of the Shadow Unmanned Aircraft engine, fuel system, and electrical system.
3. Perform troubleshooting and repair of the launcher.
4. Perform crewmember duties associated with an active Shadow Tactical Unmanned Aircraft System flightline as directed by flightline maintenance personnel.
5. Identify operations and duties of the Production Control and Quality control Shops.

Performance Standard. With supervision, given an aircraft maintenance instructional facility, surfaced fixed wing runway, computer, Shadow Unmanned Aircraft System, Personal Protective Equipment, maintenance publications and references, and forms and records, perform crewmember maintenance duties on the Shadow Unmanned Aircraft System.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References:

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. Work Center Supervisor

CSCH-6001-15E [N/A] N/A N/A B N/A C N/A Times: 1

Task. Completed all 1000 level tasks within this system.

Requirement. N/A

Performance Standard. Complete all 1000 level tasks within this system.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. NAVMC 4790.01, AMTRP Manual

Lectures. N/A

15 Jun 12

IMIs. N/AExams. N/AT&R Task Sign-Off Authority. Work Center Supervisor

2.1.2 INSPECTIONS SYSTEM (INSP). The Inspections System tasks provide the required knowledge to perform special/conditional inspections on the aircraft as it pertains to the individual's MOS. Upon completion of the Inspection System tasks, level 2000-4000, the individual shall be certified as Inspection SSP. An individual that is Inspection SSP Certified has the ability to act as the supervising authority of a task.

Table 2-02. Maintenance System "Inspections"

Maintenance Systems					
Inspection System					
INDOC	BASIC	INTERMEDIATE	ADVANCED	MGMT	QDL
N/A	2001-2027	3001-3027	4001-4027	N/A	6001

For task header description see Appendix A

INSP-2001-02010204 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 12 hour inspection (propeller re-torque).Requirement. N/APerformance Standard. With supervision, perform a 12 hour inspection (propeller re-torque).Prerequisites. N/AExternal Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2002-02010201 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 50 hour inspection (spark plug).Requirement. N/APerformance Standard. With supervision, perform a 50 hour inspection (spark plug).Prerequisites. N/AExternal Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2003-02010203 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 50 hour inspection (air filter).

Requirement. N/A

Performance Standard. With supervision, perform a 50 hour inspection (AIR FILTER).

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2004-02010202 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 50 hour inspection (fuel filter).

Requirement. N/A

Performance Standard. With supervision, perform a 50 hour inspection (fuel filter).

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2005-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 6 month inspection.

Requirement. N/A

Performance Standard. With supervision, perform a 6 month inspection.

NAVMC 4790.02

15 Jun 12

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2006-02010303 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 1 year inspection (GPS battery).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (GPS battery).

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2007-02010403 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 1 year inspection (ACE box).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (ACE box).

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2008-020109 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 1 year inspection (IFF).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (IFF).

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2009-02010404 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 1 year inspection (parachute).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (parachute).

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2010-0201 [R] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform an AV hard landing inspection.

Requirement. N/A

Performance Standard. With supervision, perform an AV hard landing inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2011-0201 [R] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform an AV inspection after net recovery.

Requirement. N/A

Performance Standard. With supervision, perform an AV inspection after net recovery.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2012-02010204 [R] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform an AV propeller strike inspection.

Requirement. N/A

Performance Standard. With supervision, perform an AV propeller strike inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2013-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform an AV post flight turn around inspection.

Requirement. N/A

Performance Standard. With supervision, perform an AV post flight turn around inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2014-830201 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a launcher pre-operational inspection.

Requirement. N/A

Performance Standard. With supervision, perform a launcher pre-operational inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2015-830201 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 6 month launcher inspection.

Requirement. N/A

Performance Standard. With supervision, perform a 6 month launcher inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2016-83020105 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a 25 launch inspection (R&R strap).

Requirement. N/A

Performance Standard. With supervision, perform a 25 launch inspection (R&R strap).

Prerequisites. N/A.

External Syllabus Support. N/A

15 Jun 12

Academics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-2017-83020106</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
---------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. With supervision, perform a 50 launch inspection (R&R cable).Requirement. N/APerformance Standard. With supervision, perform a 50 launch inspection (R&R cable).Prerequisites. N/A.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-2018-8310</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----------------------	-----	-----	-----	---	-----	---	-----	----------

Task. With supervision, perform an arresting gear weekly inspection.Requirement. N/APerformance Standard. With supervision, perform an arresting gear weekly inspection.Prerequisites. N/A.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-2019-8310</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----------------------	-----	-----	-----	---	-----	---	-----	----------

Task. With supervision, perform an arresting gear monthly inspection.Requirement. N/APerformance Standard. With supervision, perform an arresting gear monthly

inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2020-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform an arresting gear semi-annual inspection.

Requirement. N/A

Performance Standard. With supervision, perform an arresting gear semi-annual inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2021-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform an arresting gear annual/1000 arrestment inspection

Requirement. N/A

Performance Standard. With supervision, perform an arresting gear annual/1000 arrestment inspection

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

INSP-2022-830301 [S] N/A N/A B N/A A N/A Times: 1Task. With supervision, perform a GCS/GDT weekly inspection.Requirement. N/APerformance Standard. With supervision, perform a GCS/GDT weekly inspection.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARINSP-2023-830301 [S] N/A N/A B N/A A N/A Times: 1Task. With supervision, perform a GCS/GDT monthly inspection.Requirement. N/APerformance Standard. With supervision, perform a GCS/GDT monthly inspection.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARINSP-2024-830301 [S] N/A N/A B N/A A N/A Times: 1Task. With supervision, perform a GCS/GDT semi-annual inspection.Requirement. N/APerformance Standard. With supervision, perform a GCS/GDT semi-annual inspection.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2025-8304 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a PGCS/PGDT weekly inspection.

Requirement. N/A

Performance Standard. With supervision, perform a PGCS/PGDT weekly inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2026-8304 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a PGCS/PGDT semi-annual inspection.

Requirement. N/A

Performance Standard. With supervision, perform a PGCS/PGDT semi-annual inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-2027-8307 [S] N/A N/A B N/A A N/A Times: 1

Task. With supervision, perform a TALS monthly inspection.

Requirement. N/A

Performance Standard. With supervision, perform a TALS monthly inspection.

Prerequisites. N/A.

External Syllabus Support. N/A

Academics:

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3001-02010304 [S] N/A N/ B N/A A N/A Times: 1

Task. Perform a 12 hour inspection (propeller re-torque).

Requirement. N/A

Performance Standard. With supervision, perform a 12 hour inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3002-02010201 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 50 hour inspection (spark plug).

Requirement. N/A

Performance Standard. With supervision, perform a 50 hour inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3003-02010203 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 50 hour inspection (air filter).

Requirement. N/A

Performance Standard. With supervision, perform a 50 hour inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3004-02010202 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 50 hour inspection (fuel filter).

Requirement. N/A

Performance Standard. With supervision, perform a 50 hour inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3005-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 6 month inspection.

Requirement. N/A

Performance Standard. With supervision, perform a 6 month inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3006-02010303 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (GPS Battery).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (GPS battery).

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3007-02010403 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (ACE box).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (ACE box).

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3008-020109 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (IFF).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (IFF).

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3009-02010404 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (parachute).

Requirement. N/A

Performance Standard. With supervision, perform a 1 year inspection (parachute).

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

NSP-3010-0201 [R] N/A N/A B N/A A N/A Times: 1

Task. Perform an AV hard landing inspection.

Requirement. N/A

Performance Standard. With supervision, perform an AV hard landing inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3011-0201 [R] N/A N/A B N/A A N/A Times: 1

Task. Perform an AV inspection after net recovery.

Requirement. N/A

Performance Standard. With supervision, perform an AV inspection after net recovery.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3012-02010204 [R] N/A N/A B N/A A N/A Times: 1

Task. Perform an AV propeller strike inspection.

Requirement. N/A

Performance Standard. With supervision, perform an AV propeller strike inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3013-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an AV post flight turn around inspection.

Requirement. N/A

Performance Standard. With supervision, perform an AV post flight turn around inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3014-830201 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a launcher pre-operational inspection.

Requirement. N/A

Performance Standard. With supervision, perform a launcher pre-operational inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3015-830201 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 6 month launcher inspection.

Requirement. N/A

Performance Standard. With supervision, perform a 6 month launcher inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3016-83020105 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 25 launch inspection (R&R strap).

Requirement. N/A

Performance Standard. With supervision, perform a 25 launch inspection

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3017-83020106 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 50 Launch Inspection (R&R cable).

Requirement. N/A

Performance Standard. With supervision, perform a 50 Launch Inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3018-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear weekly inspection.

Requirement. N/A

Performance Standard. With supervision, perform an arresting gear weekly inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3019-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear monthly inspection.

Requirement. N/A

Performance Standard. With supervision, perform an arresting gear monthly inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3020-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear semi-annual inspection.

Requirement. N/A

Performance Standard. With supervision, perform an arresting gear semi-annual inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3021-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear annual/1000 arrestment inspection

Requirement. N/A

Performance Standard. With supervision, perform an arresting gear annual/1000 arrestment inspection

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3022-830301 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a GCS/GDT weekly inspection.

Requirement. N/A

Performance Standard. With supervision, perform a GCS/GDT weekly inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-3023-830301</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a GCS/GDT monthly inspection.Requirement. N/APerformance Standard. With supervision, perform a GCS/GDT monthly inspection.Prerequisites. Complete level 2000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-3024-830301</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a GCS/GDT semi-annual inspection.Requirement. N/APerformance Standard. With supervision, perform a GCS/GDT semi-annual inspection.Prerequisites. Complete level 2000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-3025-8304</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a PGCS/PGDT weekly inspection.Requirement. N/APerformance Standard. With supervision, perform a PGCS/PGDT weekly inspection.Prerequisites. Complete level 2000 INSP tasks.External Syllabus Support. N/AAcademics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3026-8304	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a PGCS/PGDT semi-annual inspection.

Requirement. N/A

Performance Standard. With supervision, perform a GCS/GDT semi-annual inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-3027-8307	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a TALS monthly inspection.

Requirement. N/A

Performance Standard. With supervision, perform a TALS monthly inspection.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4001-02010204	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a 12 hour inspection (propeller re-torque).

Requirement. N/A

Performance Standard. Without supervision, perform a 12 hour inspection.

Prerequisites. Complete level 3000 INSP tasks.

15 Jun 12

External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-4002-02010201</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
---------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a 50 hour inspection (spark plug).Requirement. N/APerformance Standard. Without supervision, perform a 50 hour inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-4003-02010203</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
---------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a 50 hour inspection (air filter).Requirement. N/APerformance Standard. Without supervision, perform a 50 hour inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-4004-02010202</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
---------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a 50 hour inspection (fuel filter).Requirement. N/APerformance Standard. Without supervision, perform a 50 hour inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4005-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 6 month inspection.

Requirement. N/A

Performance Standard. Without supervision, perform a 6 Month inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4006-02010303 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (GPS battery).

Requirement. N/A

Performance Standard. Without supervision, perform a 1 year inspection (GPS Battery).

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4007-02010403 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 Year inspection (ACE box).

15 Jun 12

Requirement. N/A

Performance Standard. Without supervision, perform a 1 year inspection (ACE box).

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4008-020109 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (IFF).

Requirement. N/A

Performance Standard. Without supervision, perform a 1 year inspection (IFF).

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4009-02010404 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 1 year inspection (parachute).

Requirement. N/A

Performance Standard. Without supervision, perform a 1 year inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

INSP-4010-0201 [R] N/A N/A B N/A A N/A Times: 1Task. Perform an AV hard landing inspection.Requirement. N/APerformance Standard. Without supervision, perform an AV hard landing inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARINSP-4011-0201 [R] N/A N/A B N/A A N/A Times: 1Task. Perform an AV inspection after net recovery.Requirement. N/APerformance Standard. Without supervision, perform an AV inspection after net recovery.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARINSP-4012-02010204 [R] N/A N/A B N/A A N/A Times: 1Task. Perform an AV propeller strike inspection.Requirement. N/APerformance Standard. Without supervision, perform an AV propeller strike inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-4013-0201</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform an AV post flight turn around inspection.

Requirement. N/A

Performance Standard. Without supervision, perform an AV post flight turn around inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-4014-830201</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a launcher pre-operational inspection.

Requirement. N/A

Performance Standard. Without supervision, perform a launcher pre-operational inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>INSP-4015-830201</u>	[S]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform a 6 month launcher inspection.

Requirement. N/A

Performance Standard. Without supervision, perform a 6 month launcher inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4016-83020105 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 25 launch inspection (R&R strap).

Requirement. N/A

Performance Standard. Without supervision, perform a 25 launch inspection

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4017-83020106 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a 50 launch inspection (R&R cable).

Requirement. N/A

Performance Standard. Without supervision, perform a 50 launch inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4018-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear weekly inspection.

Requirement. N/A

Performance Standard. Without supervision, perform an arresting gear weekly inspection.

Prerequisites. Complete level 3000 INSP tasks.

NAVMC 4790.02

15 Jun 12

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4019-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear monthly inspection.

Requirement. N/A

Performance Standard. Without supervision, perform an arresting gear monthly inspection.

Prerequisites. Complete level 3000 INSP tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4020-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear semi-annual inspection.

Requirement. N/A

Performance Standard. Without supervision, perform an arresting gear semi-annual inspection.

Prerequisites. Complete level 3000 INSP tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4021-8310 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform an arresting gear annual/1000 arrestment inspection

Requirement. N/A

Performance Standard. Without supervision, perform an arresting gear annual/1000 arrestment inspection

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4022-830301 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a GCS/GDT weekly inspection.

Requirement. N/A

Performance Standard. Without supervision, perform a GCS/GDT weekly inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4023-830301 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a GCS/GDT monthly inspection.

Requirement. N/A

Performance Standard. Without supervision, perform a GCS/GDT monthly inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

INSP-4024-830301 [S] N/A N/A B N/A A N/A Times: 1Task. Perform a GCS/GDT semi-annual inspection.Requirement. N/APerformance Standard. Without supervision, perform a GCS/GDT semi-annual inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARINSP-4025-8304 [S] N/A N/A B N/A A N/A Times: 1Task. Perform a PGCS/PGDT weekly inspection.Requirement. N/APerformance Standard. Without supervision, perform a PGCS/PGDT weekly inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARINSP-4026-8304 [S] N/A N/A B N/A A N/A Times: 1Task. Perform a GCS/GDT semi-annual inspection.Requirement. N/APerformance Standard. Without supervision, perform a GCS/GDT semi-annual inspection.Prerequisites. Complete level 3000 INSP tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-4027-8307 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform a TALS monthly inspection.

Requirement. N/A

Performance Standard. Without supervision, perform a TALS monthly inspection.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

INSP-6001-02010204 [S] N/A N/A B N/A A N/A Times: 1

Task. Complete INSP levels 1000 through 4000.

Requirement. N/A

Performance Standard. Complete INSP levels 1000 through 5000.

Prerequisites. Complete level 5000 INSP tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.3 CORROSION CONTROL SYSTEM (CC). The Corrosion Control System tasks provide the required knowledge to perform corrosion control on the Shadow UAS system as it pertains to the individual's MOS. Upon completion of the Corrosion Control System tasks, level 2000-4000, the individual shall be certified as Corrosion Control SSP. An individual that is Corrosion Control SSP Certified has the ability to act as the supervising authority of a task.

Table 2-03. Maintenance System "Corrosion Control"

Maintenance System

Corrosion Control					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2004	3001-3003	4001-4003	N/A	6001

NOTE

For task header description see Appendix A

CORS-2001 [Z] N/A N/A B N/A A N/A Times: 1

Task. Perform corrosion prevention during all maintenance actions.

Requirement. N/A

Performance Standard. With supervision, perform corrosion control during all maintenance actions.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. NAVAIR 16-1-540, NAVAIR 01-1A-509

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-2002-XXXX [Z] N/A N/A B N/A A N/A Times: 1

Task. Identify corrosion during all maintenance actions.

Requirement. N/A

Performance Standard. With supervision, identify corrosion during all maintenance actions.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. NAVAIR 16-1-540, NAVAIR 01-1A-509

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-2003-XXXX [Z] N/A N/A B N/A A N/A Times: 1

Task. Perform corrective action on corrosion discrepancy.

Requirement. N/A

Performance Standard. With supervision, perform corrective action on

corrosion discrepancy.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. NAVAIR 16-1-540, NAVAIR 01-1A-509

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-2004-XXXX [Z] N/A N/A B N/A A N/A Times: 1

Task. Perform corrosion prevention/detection on support equipment.

Requirement. N/A

Performance Standard. With supervision, perform corrosion prevention/detection on support equipment.

Prerequisites. N/A

External Syllabus Support. N/A

Academics:

References. NAVAIR 17-1-125

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-3001-XXXX [Z] N/A N/A B N/A A N/A Times: 1

Task. Identify corrosion during all maintenance actions.

Requirement. N/A

Performance Standard. With supervision, identify corrosion during all maintenance actions.

Prerequisites. Complete level 2000 CORS tasks.

External Syllabus Support. N/A

Academics:

References. NAVAIR 16-1-540, NAVAIR 01-1A-509

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-3002-XXXX [Z] N/A N/A B N/A A N/A Times: 1

15 Jun 12

Task. Perform corrective action on corrosion discrepancy.Requirement. N/APerformance Standard. With supervision, perform corrective action on corrosion discrepancy.Prerequisites. Complete level 2000 CORS tasks.External Syllabus Support. N/AAcademics:References. NAVAIR 16-1-540, NAVAIR 01-1A-509Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-3003-XXXX	[Z]	N/A	N/A	B.	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	----	-----	---	-----	----------

Task. Perform corrosion prevention/detection on support equipment.Requirement. N/APerformance Standard. With supervision, perform corrosion prevention/detection on support equipment.Prerequisites. Complete level 2000 CORS tasks.External Syllabus Support. N/AAcademics:References. NAVAIR 17-1-125Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-4001-XXXX	[Z]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Identify corrosion during all maintenance actions.Requirement. N/APerformance Standard. Without supervision, identify corrosion during all maintenance actions.Prerequisites. Complete level 3000 CORS tasks.External Syllabus Support. N/AAcademics:References. NAVAIR 16-1-540, NAVAIR 01-1A-509Lectures. N/AIMIs. N/AExams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-4002-XXXX	[Z]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform corrective action on corrosion discrepancy.

Requirement. N/A

Performance Standard. Without supervision, perform corrective action on corrosion discrepancy.

Prerequisites. Complete level 3000 CORS tasks.

External Syllabus Support. N/A

Academics:

References. NAVAIR 16-1-540, NAVAIR 01-1A-509

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-4003-XXXX	[Z]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform corrosion prevention/detection on support equipment.

Requirement. N/A

Performance Standard. Without supervision, perform corrosion prevention/detection on support equipment.

Prerequisites. Complete level 2000 CORS tasks.

External Syllabus Support. N/A

Academics:

References. NAVAIR 17-1-125

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

CORS-6001-XXXX	[Z]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Complete CORS levels 1000 through 5000.

Requirement. N/A

Performance Standard. Complete CORS levels 1000 through 5000.

Prerequisites. Complete level 4000 CORS tasks.

External Syllabus Support. N/A

Academics:

References. NAVAIR 16-1-540, NAVAIR 01-1A-509

Lectures. N/A

IMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.4 UNMANNED AIR VEHICLE SYSTEM (UAVS). The Unmanned Air Vehicle System (UAVS) tasks provide the required knowledge to perform all aspects of maintenance on the Shadow 200 Air Vehicle as it pertains to the individual's MOS. Upon completion of the Air Vehicle System tasks, level 2000-4000, the individual shall be certified as Air Vehicle SSP. An individual that is Air Vehicle SSP Certified has the ability to act as the supervising authority of a task.

Table 2-04. Maintenance System "Unmanned Air Vehicle"

Maintenance Systems					
Unmanned Air Vehicle					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2019	3001-3019	4001-4019	N/A	6001

NOTE

For task header description see Appendix A

UAVS-2001-0201 [A] N/A N/A B N/A A N/A Times: 1

Task. Assemble the air vehicle.Requirement. N/APerformance Standard. With supervision, assemble the air vehicle.Prerequisites. Complete level 1000 tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2002-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. Disassemble the air vehicle.Requirement. N/APerformance Standard. With supervision, disassemble the air vehicle.Prerequisites. N/AExternal Syllabus Support. N/AAcademics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2003-020117 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove wings.

Requirement. N/A

Performance Standard. With supervision, remove wings.

Prerequisites. Complete level 1000 tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2004-020117 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install wings.

Requirement. N/A

Performance Standard. With supervision, install wings.

Prerequisites. Complete level 1000 tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2005-020119 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove booms.

Requirement. N/A

Performance Standard. With supervision, remove booms.

Prerequisites. Complete level 1000 tasks.

External Syllabus Support. N/A

15 Jun 12

Academics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2006-020119	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install booms.Requirement. N/APerformance Standard. With supervision, install booms.Prerequisites. Complete level 1000 tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2007-020116	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove empennage assembly.Requirement. N/APerformance Standard. With supervision, remove empennage assembly.Prerequisites. Complete level 1000 tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2008-020116	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install empennage assembly.Requirement. N/APerformance Standard. With supervision, install empennage assembly.Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2009-020116 [S] N/A N/A B N/A A N/A Times: 1

Task. Perform the displacement of empennage assembly.

Requirement. N/A

Performance Standard. With supervision, perform displacement of empennage assembly.

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2010-0201062 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove nose landing gear (NLG).

Requirement. N/A

Performance Standard. With supervision, remove nose landing gear (NLG).

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2011-0201062 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install nose landing gear (NLG).

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. With supervision, install nose landing gear (NLG).

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2012-02010601 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove main landing gear (MLG).

Requirement. N/A

Performance Standard. With supervision, remove main landing gear (MLG).

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2013-02010601 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install main landing gear (MLG).

Requirement. N/A

Performance Standard. With supervision, install main landing gear (MLG).

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2014-0201060101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove main landing gear wheel assembly.

Requirement. N/A

Performance Standard. With supervision, remove main landing gear wheel assembly.

Prerequisites. Complete level 1000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2015-0201060101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install main landing gear wheel assembly.

Requirement. N/A

Performance Standard. With supervision, install main landing gear wheel assembly.

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2016-0201060104 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting hook assembly.

Requirement. N/A

Performance Standard. With supervision, remove arresting hook assembly.

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

NAVMC 4790.02

15 Jun 12

UAVS-2017-0201060104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting hook assembly.

Requirement. N/A

Performance Standard. With supervision, install arresting hook assembly.

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2018-02010702 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting pad.

Requirement. N/A

Performance Standard. With supervision, remove arresting pad.

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-2019-02010702 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting pad.

Requirement. N/A

Performance Standard. With supervision, install arresting pad.

Prerequisites. Complete level 1000 UAVS tasks..

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3001-0201 [A] N/A N/A B N/A A N/A Times: 1

Task. Assemble the air vehicle.

Requirement. N/A

Performance Standard. With supervision, assemble the air vehicle.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3002-0201 [S] N/A N/A B N/A A N/A Times: 1

Task. Disassemble the air vehicle.

Requirement. N/A

Performance Standard. With supervision, disassemble the air vehicle.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3003-020117 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove wings.

Requirement. N/A

Performance Standard. With supervision, remove wings.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3004-020117 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install wings.

Requirement. N/A

Performance Standard. With supervision, install wings.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3005-020119 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove booms.

Requirement. N/A

Performance Standard. With supervision, remove booms.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3006-020119 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install booms.

Requirement. N/A

Performance Standard. With supervision, install booms.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3007-020116 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove empennage assembly.

Requirement. N/A

Performance Standard. With supervision, remove empennage assembly.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3008-020116 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install empennage assembly.

Requirement. N/A

Performance Standard. With supervision, install empennage assembly.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3009-020116 [S] N/A N/A B N/A A N/A Times: 1

Task. Displace empennage assembly.

Requirement. N/A

Performance Standard. With supervision, displace empennage assembly.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3010-0201062	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove nose landing gear (NLG).Requirement. N/APerformance Standard. With supervision, remove nose landing gear (NLG).Prerequisites. Complete level 2000 UAVS tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3011-0201062	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install nose landing gear (NLG).Requirement. N/APerformance Standard. With supervision, install nose landing gear (NLG).Prerequisites. Complete level 2000 UAVS tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3012-02010601	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove main landing gear (MLG).Requirement. N/APerformance Standard. With supervision, remove main landing gear (MLG).Prerequisites. Complete level 2000 UAVS tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3013-02010601 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install main landing gear (MLG).

Requirement. N/A

Performance Standard. With supervision, install main landing gear (MLG).

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3014-0201060101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove main landing gear wheel assembly.

Requirement. N/A

Performance Standard. With supervision, remove main landing gear wheel assembly.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3015-0201060101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install main landing gear wheel assembly.

Requirement. N/A

Performance Standard. With supervision, install main landing gear wheel assembly.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3016-0201060104 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting hook assembly.

Requirement. N/A

Performance Standard. With supervision, remove arresting hook assembly.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3017-0201060104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting hook assembly.

Requirement. N/A

Performance Standard. With supervision, install arresting hook assembly.

Prerequisites. Complete level 2000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3018-02010702 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting pad.

Requirement. N/A

Performance Standard. With supervision, remove arresting pad.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-3019-02010702 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting pad.

Requirement. N/A

Performance Standard. With supervision, install arresting pad.

Prerequisites. Complete level 2000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4001-0201 [A] N/A N/A B N/A A N/A Times: 1

Task. Assemble the air vehicle.

Requirement. N/A

Performance Standard. Without supervision, assemble the air vehicle.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4002-0201 [X] N/A N/A B N/A A N/A Times: 1

Task. Disassemble the air vehicle.

Requirement. N/A

Performance Standard. Without supervision, disassemble the air vehicle.

Prerequisites. Complete level 3000 UAVS tasks.

NAVMC 4790.02

15 Jun 12

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4003-020117 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove wings.

Requirement. N/A

Performance Standard. Without supervision, remove wings.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4004-020117 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install wings.

Requirement. N/A

Performance Standard. Without supervision, install wings.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4005-020119 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove booms.

Requirement. N/A

Performance Standard. Without supervision, remove booms.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4006-020119 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install booms.

Requirement. N/A

Performance Standard. Without supervision, install booms.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4007-020116 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove empennage assembly.

Requirement. N/A

Performance Standard. Without supervision, remove empennage assembly.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4008-020116 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install empennage assembly.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. Without supervision, install empennage assembly.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4009-020116 [S] N/A N/A B N/A A N/A Times: 1

Task. Displace empennage assembly.

Requirement. N/A

Performance Standard. Without supervision, displace empennage assembly.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4010-0201062 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove nose landing gear (NLG).

Requirement. N/A

Performance Standard. Without supervision, remove nose landing gear (NLG).

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4011-0201062 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install nose landing gear (NLG).

Requirement. N/A

Performance Standard. Without supervision, install nose landing gear (NLG).

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4012-02010601 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove main landing gear (MLG).

Requirement. N/A

Performance Standard. Without supervision, remove main landing gear (MLG).

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4013-02010601 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install main landing gear (MLG).

Requirement. N/A

Performance Standard. Without supervision, install main landing gear (MLG).

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARUAVS-4014-0201060101 [P] N/A N/A B N/A A N/A Times: 1Task. Remove main landing gear wheel assembly.Requirement. N/APerformance Standard. Without supervision, remove main landing gear wheel assembly.Prerequisites. Complete level 3000 UAVS tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARUAVS-4015-0201060101 [Q] N/A N/A B N/A A N/A Times: 1Task. Install main landing gear wheel assembly.Requirement. N/APerformance Standard. Without supervision, install main landing gear wheel assembly.Prerequisites. Complete level 3000 UAVS tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARUAVS-4016-0201060104 [P] N/A N/A B N/A A N/A Times: 1Task. Remove arresting hook assembly.Requirement. N/APerformance Standard. Without supervision, remove arresting hook assembly.Prerequisites. Complete level 3000 UAVS tasks.External Syllabus Support. N/AAcademics:References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4017-0201060104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting hook assembly.

Requirement. N/A

Performance Standard. Without supervision, install arresting hook assembly.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4018-02010702 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting pad.

Requirement. N/A

Performance Standard. Without supervision, remove arresting pad.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

UAVS-4019-02010702 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting pad.

Requirement. N/A

Performance Standard. Without supervision, install arresting pad.

Prerequisites. Complete level 3000 UAVS tasks.

External Syllabus Support. N/A

15 Jun 12

Academics:References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

<u>UAVS-6001-0201</u>	[N/A]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Complete UAVS levels 1000 through 4000.

Requirement. N/APerformance Standard. Complete UAVS levels 1000 through 4000.Prerequisites. Complete level 4000 INSP tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.5 ENGINE/PROPULSION SYSTEM (ENGS). The Engine/Propulsion System (ENG) tasks provide the required knowledge to perform engine maintenance on the aircraft as it pertains to the individual's MOS. Upon completion of the Engine /Propulsion System tasks, level 2000-4000, the individual shall be certified as Engine/Propulsion System SSP. An individual that is Engine/Propulsion System SSP Certified has the ability to act as the supervising authority of a task.

Table 2-05. Maintenance System "Engine/Propulsion System"

Maintenance Systems					
Engine/Propulsion System (ENGS)					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2012	3001-3012	4001-4012	N/A	6001

NOTE

For task header description see Appendix A

<u>ENGS-2001-020102</u>	[E]	N/A	N/A	B	N/A	A	N/A	Times: 1
-------------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform engine/propulsion system functional check.

Requirement. N/A

Performance Standard. With supervision, perform engine/propulsion system functional check.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2002-020102 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform engine/propulsion system fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform engine/propulsion system fault isolation.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2003-020102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove engine.

Requirement. N/A

Performance Standard. With supervision, remove engine.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

NAVMC 4790.02

15 Jun 12

ENGS-2004-020102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install engine.

Requirement. N/A

Performance Standard. With supervision, install engine.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2005-02010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove spark plugs.

Requirement. N/A

Performance Standard. With supervision, remove spark plugs.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2006-02010201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install spark plugs.

Requirement. N/A

Performance Standard. With supervision, install spark plugs.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2007-020102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove intake covers.

Requirement. N/A

Performance Standard. With supervision, remove intake covers.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2008-020102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install intake covers.

Requirement. N/A

Performance Standard. With supervision, install intake covers.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-2009-02010204 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove propeller.

Requirement. N/A

Performance Standard. With supervision, remove propeller.

Prerequisites. Complete level 1000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARENGS-2010-02010204 [Q] N/A N/A B N/A A N/A Times: 1Task. Install propeller.Requirement. N/APerformance Standard. With supervision, install propeller.Prerequisites. Complete level 1000 ENGS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARENGS-2011-02010203 [P] N/A N/A B N/A A N/A Times: 1Task. Remove air filter.Requirement. N/APerformance Standard. With supervision, remove air filter.Prerequisites. Complete level 1000 ENGS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARENGS-2012-02010203 [Q] N/A N/A B N/A A N/A Times: 1Task. Install air filter.Requirement. N/APerformance Standard. With supervision, install air filter.Prerequisites. Complete level 1000 ENGS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3001-020102 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform engine/propulsion system functional check.

Requirement. N/A

Performance Standard. With supervision, perform engine/propulsion system functional check.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3002-020102 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform engine/propulsion system fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform engine/propulsion system fault isolation.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3003-020102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove engine.

Requirement. N/A

Performance Standard. With supervision, Remove engine.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

NAVMC 4790.02

15 Jun 12

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3004-020102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install engine.

Requirement. N/A

Performance Standard. With supervision, install engine.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3005-02010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove spark plugs.

Requirement. N/A

Performance Standard. With supervision, remove spark plugs.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3006-02010201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install spark plugs.

Requirement. N/A

Performance Standard. With supervision, install spark plugs.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3007-020102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove intake covers.

Requirement. N/A

Performance Standard. With supervision, remove intake covers.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3008-020102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install intake covers.

Requirement. N/A

Performance Standard. With supervision, install intake covers.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3009-02010204 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove propeller.

Requirement. N/A

Performance Standard. With supervision, remove propeller.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3010-02010204 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install propeller.

Requirement. N/A

Performance Standard. With supervision, install propeller.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3011-02010203 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air filter.

Requirement. N/A

Performance Standard. With supervision, remove air filter.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-3012-02010203 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air filter.

Requirement. N/A

Performance Standard. With supervision, install air filter.

Prerequisites. Complete level 2000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4001-020102 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform engine/propulsion system functional check.

Requirement. N/A

Performance Standard. Without supervision, perform engine/propulsion system functional check.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4002-020102 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform engine/propulsion system fault isolation.

Requirement. N/A

Performance Standard. Without supervision, perform engine/propulsion system fault isolation.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4003-020102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove engine.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. Without supervision, remove engine.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4004-020102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install Engine.

Requirement. N/A

Performance Standard. Without supervision, install engine.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4005-02010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove spark plugs.

Requirement. N/A

Performance Standard. Without supervision, remove spark plugs.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4006-02010201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install spark plugs.

Requirement. N/A

Performance Standard. Without supervision, install spark plugs.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4007-020102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove intake covers.

Requirement. N/A

Performance Standard. Without supervision, remove intake covers.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4008-020102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install intake covers.

Requirement. N/A

Performance Standard. Without supervision, install intake covers.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4009-02010204 [P] N/A N/A B N/A A N/A Times: 1

NAVMC 4790.02

15 Jun 12

Task. Remove propeller.

Requirement. N/A

Performance Standard. Without supervision, remove propeller.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4010-02010204 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install propeller.

Requirement. N/A

Performance Standard. Without supervision, install propeller.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-4011-02010203 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air filter.

Requirement. N/A

Performance Standard. Without supervision, remove air filter.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

ENGS-4012-02010203	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install air filter.

Requirement. N/A

Performance Standard. Without supervision, install air filter.

Prerequisites. Complete level 3000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

ENGS-6001-020102	[N/A]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Complete ENGS 1000 through 4000 tasks.

Requirement. N/A

Performance Standard. Complete ENGS 1000 through 4000 tasks.

Prerequisites. Complete level 4000 ENGS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.6 FUEL SYSTEM. The Fuel System tasks provide the required knowledge to perform all aspects of maintenance on the aircraft fuel system as it pertains to the individual's MOS. Upon completion of the Fuel System tasks, level 2000-4000, the individual shall be certified as Fuel System SSP. An individual that is Fuel System SSP Certified has the ability to act as the supervising authority of a task.

Table 2-06. Maintenance System "Fuel System"

Maintenance Systems					
Fuel System					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2003	3001-3003	4001-4003	N/A	6001

NOTE

For task header description see Appendix A

FUEL-2001-02010202 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform fuel system functional check.

Requirement. N/A

Performance Standard. With supervision, perform fuel system functional check.

Prerequisites. Complete level 1000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-2002-02010202 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove inline fuel filter.

Requirement. N/A

Performance Standard. With supervision, remove inline fuel filter.

Prerequisites. Complete level 1000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams: N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-2003-02010202 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install inline fuel filter.

Requirement. N/A

Performance Standard. With supervision, install inline fuel filter.

Prerequisites. Complete level 1000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-3001-02010202 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform fuel system functional check.

Requirement. N/A

Performance Standard. With supervision, perform fuel system functional check.

Prerequisites. Complete level 2000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-3002-02010202 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove inline fuel filter.

Requirement. N/A

Performance Standard. With supervision, remove inline fuel filter.

Prerequisites. Complete level 2000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-3003-02010202 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install inline fuel filter.

Requirement. N/A

Performance Standard. With supervision, install inline fuel filter.

Prerequisites. Complete level 2000 FUEL tasks.

NAVMC 4790.02

15 Jun 12

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-4001-02010202 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform fuel system functional check.

Requirement. N/A

Performance Standard. Without supervision, perform fuel system functional check.

Prerequisites. Complete level 3000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-4002-02010202 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove inline fuel filter.

Requirement. N/A

Performance Standard. Without supervision, remove inline fuel filter.

Prerequisites. Complete level 3000 FUEL tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-4003-02010202 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install inline fuel filter.

Requirement. N/A

15 Jun 12

Performance Standard. Without supervision, install inline fuel filter.Prerequisites. Complete level 3000 FUEL tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

FUEL-6001-02010202	[N/A]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Complete FUEL 1000 through 4000 tasks.Requirement. N/APerformance Standard. Complete FUEL 1000 through 4000 tasks.Prerequisites. Complete level 4000 FUEL tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-NFM-000Lectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.7 LAUNCHER SYSTEM (LAUN). The Launcher System (LAU) tasks provide the required knowledge to perform all aspects of maintenance on the Launcher System as it pertains to the individual's MOS. Upon completion of the Launcher System tasks, level 2000-4000, the individual shall be certified as Launcher SSP. An individual that is Launcher SSP Certified has the ability to act as the supervising authority of a task.

Table 2-07. Maintenance System "Launcher" (LAUN)

Maintenance Systems					
Launcher System (LAU)					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2000-2011	3000-3011	4000-4011	N/A	6000

NOTE

For task header description see Appendix A

15 Jun 12

LAUN-2001-83020105 [P] N/A N/A B N/A A N/A Times: 1Task. Remove arresting strap.Requirement. N/APerformance Standard. With supervision, remove arresting strap.Prerequisites. Complete level 1000 LAUN tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARLAUN-2002-83020105 [Q] N/A N/A B N/A A N/A Times: 1Task. Install arresting strap.Requirement. N/APerformance Standard. With supervision, install arresting strap.Prerequisites. Complete level 1000 LAUN tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARLAUN-2003-830201 [P] N/A N/A B N/A A N/A Times: 1Task. Remove light bulbs in launcher electrical control unit.Requirement. N/APerformance Standard. With supervision, remove light bulbs in launcher electrical control unit.Prerequisites. Complete level 1000 LAUN tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2004-830201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install light bulbs in launcher electrical control unit.

Requirement. N/A

Performance Standard. With supervision, install light bulbs in launcher electrical control unit.

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2005-83020101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove light bulbs in launcher hand control unit.

Requirement. N/A

Performance Standard. With supervision, remove light bulbs in launcher hand control unit.

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2006-83020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install light bulbs in launcher hand control unit.

Requirement. N/A

Performance Standard. With supervision, install light bulbs in launcher hand control unit.

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

NAVMC 4790.02

15 Jun 12

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2007-83020104 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove ground power unit (GPU).

Requirement. N/A

Performance Standard. With supervision, remove ground power unit (GPU).

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2008-83020104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install ground power unit (GPU).

Requirement. N/A

Performance Standard. With supervision, install ground power unit (GPU).

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2009-831002 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting gear pendant.

Requirement. N/A

Performance Standard. With supervision, remove arresting gear pendant.

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-2010-831002 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting gear pendant.

Requirement. N/A

Performance Standard. With supervision, install arresting gear pendant.

Prerequisites. Complete level 1000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3001-83020105 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting strap.

Requirement. N/A

Performance Standard. With supervision, remove arresting strap.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3002-83020105 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting strap.

Requirement. N/A

Performance Standard. With supervision, install arresting strap.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3003-830201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove light bulbs in launcher electrical control unit.

Requirement. N/A

Performance Standard. With supervision, remove light bulbs in launcher electrical control unit.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3004-830201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install light bulbs in launcher electrical control unit.

Requirement. N/A

Performance Standard. With supervision, install light bulbs in launcher electrical control unit.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3005-83020101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove light bulbs in launcher hand control unit.

Requirement. N/A

Performance Standard. With supervision, remove light bulbs in launcher

hand control unit.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3006-83020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install light bulbs in launcher hand control unit.

Requirement. N/A

Performance Standard. With supervision, install light bulbs in launcher hand control unit.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3007-83020104 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove ground power unit (GPU).

Requirement. N/A

Performance Standard. With supervision, remove ground power unit (GPU).

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3008-83020104 [Q] N/A N/A B N/A A N/A Times: 1

NAVMC 4790.02

15 Jun 12

Task. Install ground power unit (GPU).

Requirement. N/A

Performance Standard. With supervision, install ground power unit (GPU).

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3009-831002 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting gear pendant.

Requirement. N/A

Performance Standard. With supervision, remove arresting gear pendant.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-3010-831002 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting gear pendant.

Requirement. N/A

Performance Standard. With supervision, install arresting gear pendant.

Prerequisites. Complete level 2000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

LAUN-4001-83020105	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove arresting strap.

Requirement. N/A

Performance Standard. Without supervision, remove arresting strap.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4002-83020105	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install arresting strap.

Requirement. N/A

Performance Standard. Without supervision, install arresting strap.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4003-830201	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove light bulbs in launcher electrical control unit.

Requirement. N/A

Performance Standard. Without supervision, remove light bulbs in launcher electrical control unit.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4004-830201	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install light bulbs in launcher electrical control unit.

Requirement. N/A

Performance Standard. Without supervision, install light bulbs in launcher electrical control unit.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4005-83020101	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove light bulbs in launcher hand control unit.

Requirement. N/A

Performance Standard. Without supervision, remove light bulbs in launcher hand control unit.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4006-83020101	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install light bulbs in launcher hand control unit.

Requirement. N/A

Performance Standard. Without supervision, install light bulbs in launcher hand control unit.

Prerequisites. Complete level 3000 LAUN system tasks

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4007-83020104 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove ground power unit (GPU).

Requirement. N/A

Performance Standard. Without supervision, remove ground power unit (GPU).

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4008-83020104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install ground power unit (GPU).

Requirement. N/A

Performance Standard. Without supervision, install ground power unit (GPU).

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4009-831002 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove arresting gear pendant.

Requirement. N/A

Performance Standard. Without supervision, remove arresting gear pendant.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-4010-831002 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install arresting gear pendant.

Requirement. N/A

Performance Standard. Without supervision, install arresting gear pendant.

Prerequisites. Complete level 3000 LAUN tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

LAUN-6001-83020105 [N/A] N/A N/A B N/A A N/A Times: 1

Task. Complete level 1000 through 4000 LAUN tasks.

Requirement. N/A

Performance Standard. Complete level 1000 through 4000 LAUN tasks..

Prerequisites. Complete level 4000 Tasks

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.8 AIRCRAFT AVIONICS SYSTEM (AVIS). The Aircraft Avionics System (AVI) tasks provide the required knowledge to perform all aspects of maintenance on the Shadow 200 Air Vehicle Avionics Package as it pertains to the individual's MOS. Upon completion of the Air Vehicle Avionics System tasks, level 2000-4000, the individual shall be certified as Aircraft Avionics SSP. An individual that is Aircraft Avionics SSP Certified has the ability to act

as the supervising authority of a task.

Table 2-08. Maintenance System "Aircraft Avionics" (AVI)

Maintenance Systems					
Aircraft Avionics System (AVI)					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2026	3001-3026	4001-4026	N/A	6001

NOTE

For task header description see Appendix A

AVIS-2001-020111 [L] N/A N/A B N/A A N/A Times: 1

Task. Modem programming.

Requirement. N/A

Performance Standard. With supervision, perform modem programming.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2002-02010403 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove airborne computer equipment (ACE) II box.

Requirement. N/A

Performance Standard. With supervision, remove airborne computer equipment (ACE) II box.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2003-02010403 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install airborne computer equipment (ACE)II box.

Requirement. N/A

Performance Standard. With supervision, install airborne computer equipment (ACE)II box.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2004-02010303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air vehicle battery.

Requirement. N/A

Performance Standard. With supervision, remove air vehicle battery.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2005-02010303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air vehicle battery.

Requirement. N/A

Performance Standard. With supervision, install air vehicle battery.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2006-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF antenna.

Requirement. N/A

Performance Standard. With supervision, remove IFF antenna.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2007-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF antenna.

Requirement. N/A

Performance Standard. With supervision, install IFF antenna.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2008-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF transponder.

Requirement. N/A

Performance Standard. With supervision, remove IFF transponder.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2009-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF transponder.

Requirement. N/A

Performance Standard. With supervision, install IFF transponder.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2010-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF transponder battery.

Requirement. N/A

Performance Standard. With supervision, remove IFF transponder battery.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2011-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF transponder battery.

Requirement. N/A

Performance Standard. With supervision, install IFF transponder battery.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2012-020103 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove power distribution unit (PDU).

Requirement. N/A

Performance Standard. With supervision, remove power distribution unit (PDU).

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2013-020103 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install power distribution unit (PDU).

Requirement. N/A

Performance Standard. With supervision, install power distribution unit (PDU).

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2014-020101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove POP payload.

Requirement. N/A

Performance Standard. With supervision, remove POP payload.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2015-020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install POP payload.

Requirement. N/A

Performance Standard. With supervision, install POP payload.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2016-02010502 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air vehicle navigation lights.

Requirement. N/A

Performance Standard. With supervision, remove air vehicle navigation lights.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2017-02010502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air vehicle navigation lights.

Requirement. N/A

Performance Standard. With supervision, install air vehicle navigation lights.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2018-02010501 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove strobe light assembly.

Requirement. N/A

Performance Standard. With supervision, with supervision, remove strobe light assembly.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2019-02010501 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install strobe light assembly.

Requirement. N/A

Performance Standard. With supervision, install strobe light assembly.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2020-0201050101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove strobe light power supply.

NAVMC 4790.02

15 Jun 12

Requirement. N/A

Performance Standard. With supervision, remove strobe light power supply.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2021-0201050101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install strobe light power supply.

Requirement. N/A

Performance Standard. With supervision, install strobe light power supply.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2022-020108 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GPS antenna.

Requirement. N/A

Performance Standard. With supervision, remove GPS antenna.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

AVIS-2023-020108	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install GPS antenna.

Requirement. N/A

Performance Standard. With supervision, install GPS Antenna.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2024-020111	[Y]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform air vehicle communications fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform air vehicle communications fault isolation.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-2025-020111	[Y]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform air vehicle avionics fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform air vehicle avionics fault isolation.

Prerequisites. Complete level 1000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARAVIS-2026-020110 [L] N/A N/A B N/A A N/A Times: 1Task. Set video signal frequency.Requirement. N/APerformance Standard. With supervision, set video signal frequency.Prerequisites. Complete level 1000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARAVIS-3001-020111 [L] N/A N/A B N/A A N/A Times: 1Task. Perform modem programming.Requirement. N/APerformance Standard. With supervision, perform modem programming.Prerequisites. Complete level 2000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARAVIS-3002-02010403 [P] N/A N/A B N/A A N/A Times: 1Task. Remove airborne computer equipment (ACE) II box.Requirement. N/APerformance Standard. With supervision, remove airborne computer equipment (ACE) II box.Prerequisites. Complete level 2000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3003-02010403 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install airborne computer equipment (ACE)II box.

Requirement. N/A

Performance Standard. With supervision, install airborne computer equipment (ACE)II box.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3004-02010303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air vehicle battery.

Requirement. N/A

Performance Standard. With supervision, remove air vehicle battery.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3005-02010303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air vehicle battery.

Requirement. N/A

Performance Standard. With supervision, install air vehicle battery.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3006-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF antenna.

Requirement. N/A

Performance Standard. With supervision, remove IFF antenna.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3007-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF antenna.

Requirement. N/A

Performance Standard. With supervision, install IFF antenna.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3008-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF transponder.

Requirement. N/A

Performance Standard. With supervision, remove IFF transponder.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3009-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF transponder.

Requirement. N/A

Performance Standard. With supervision, install IFF transponder.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3010-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF transponder battery.

Requirement. N/A

Performance Standard. With supervision, remove IFF transponder battery.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3011-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF transponder battery.

Requirement. N/A

Performance Standard. With supervision, install IFF transponder battery.

Prerequisites. Complete level 2000 AVIS tasks.

15 Jun 12

External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3012-020103	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove power distribution unit (PDU).Requirement. N/APerformance Standard. With supervision, remove power distribution unit (PDU).Prerequisites. Complete level 2000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3013-020103	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install power distribution unit (PDU).Requirement. N/APerformance Standard. With supervision, install power distribution unit (PDU).Prerequisites. Complete level 2000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3014-020101	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove POP payload.Requirement. N/A

Performance Standard. With supervision, remove POP payload.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3015-020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install POP payload.

Requirement. N/A

Performance Standard. With supervision, install POP payload.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3016-02010502 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air vehicle navigation lights.

Requirement. N/A

Performance Standard. With supervision, remove air vehicle navigation lights.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3017-02010502 [Q] N/A N/A B N/A A N/A Times: 1

NAVMC 4790.02

15 Jun 12

Task. Install air vehicle navigation lights.

Requirement. N/A

Performance Standard. With supervision, install air vehicle navigation lights.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3018-02010501 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove strobe light assembly.

Requirement. N/A

Performance Standard. With supervision, remove strobe light assembly.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3019-02010501 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install strobe light assembly.

Requirement. N/A

Performance Standard. With supervision, install strobe light assembly.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3020-0201050101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove strobe light power supply.

Requirement. N/A

Performance Standard. With supervision, remove strobe light power supply.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3021-0201050101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install strobe light power supply.

Requirement. N/A

Performance Standard. With supervision, install strobe light power supply.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3022-020108 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GPS antenna.

Requirement. N/A

Performance Standard. With supervision, remove GPS antenna.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

NAVMC 4790.02

15 Jun 12

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3023-020108 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GPS antenna.

Requirement. N/A

Performance Standard. With supervision, install GPS antenna.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3024-020111 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform air vehicle communications fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform air vehicle communications fault isolation.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3025-020111 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform air vehicle avionics fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform air vehicle avionics fault isolation.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-3026-020110 [L] N/A N/A B N/A A N/A Times: 1

Task. Set video signal frequency.

Requirement. N/A

Performance Standard. With supervision, set video signal frequency.

Prerequisites. Complete level 2000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4001-020111 [L] N/A N/A B N/A A N/A Times: 1

Task. Modem programming.

Requirement. N/A

Performance Standard. Without supervision, perform modem programming.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4002-02010403 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove airborne computer equipment (ACE)II box.

Requirement. N/A

Performance Standard. Without supervision, remove airborne computer equipment (ACE)II box.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4003-02010403 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install airborne computer equipment (ACE)II box.

Requirement. N/A

Performance Standard. Without supervision, install airborne computer equipment (ACE)II box.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4004-02010303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air vehicle battery.

Requirement. N/A

Performance Standard. Without supervision, remove air vehicle battery.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4005-02010303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air vehicle battery.

Requirement. N/A

Performance Standard. Without supervision, install air vehicle battery.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4006-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF antenna.

Requirement. N/A

Performance Standard. Without supervision, remove IFF antenna.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4007-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF antenna.

Requirement. N/A

Performance Standard. Without supervision, install IFF antenna.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4008-020109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF transponder.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. Without supervision, remove IFF transponder.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4009-020109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF transponder.

Requirement. N/A

Performance Standard. Without supervision, install IFF transponder.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4010-02010303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove IFF transponder battery.

Requirement. N/A

Performance Standard. Without supervision, remove IFF transponder Battery.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4011-02010303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install IFF transponder battery.

Requirement. N/A

Performance Standard. Without supervision, install IFF transponder Battery.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4012-020103 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove power distribution unit (PDU).

Requirement. N/A

Performance Standard. Without supervision, remove power distribution unit (PDU).

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4013-020103 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install power distribution unit (PDU).

Requirement. N/A

Performance Standard. Without supervision, install power distribution unit (PDU).

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARAVIS-4014-020101 [P] N/A N/A B N/A A N/A Times: 1Task. Remove payload.Requirement. N/APerformance Standard. Without supervision, remove payload.Prerequisites. Complete level 3000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARAVIS-4015-020101 [Q] N/A N/A B N/A A N/A Times: 1Task. Install payload.Requirement. N/APerformance Standard. Without supervision, install payload.Prerequisites. Complete level 3000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARAVIS-4016-02010502 [P] N/A N/A B N/A A N/A Times: 1Task. Remove air vehicle navigation lights.Requirement. N/APerformance Standard. Without supervision, remove air vehicle navigation lights.Prerequisites. Complete level 3000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4017-02010502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air vehicle navigation lights.

Requirement. N/A

Performance Standard. Without supervision, install air vehicle navigation lights.

Prerequisites. Complete level 3000 INSP tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4018-02010501 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove strobe light assembly.

Requirement. N/A

Performance Standard. Without supervision, remove strobe light assembly.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4019-02010501 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install strobe light assembly.

Requirement. N/A

Performance Standard. Without supervision, install strobe light assembly.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

15 Jun 12

References. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4020-0201050101	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove strobe light power supply.Requirement. N/APerformance Standard. Without supervision, remove strobe light power supply.Prerequisites. Complete level 3000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4021-0201050101	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install strobe light power supply.Requirement. N/APerformance Standard. Without supervision, install strobe light power supply.Prerequisites. Complete level 3000 AVIS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4022-020108	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove GPS antenna.Requirement. N/APerformance Standard. Without supervision, remove GPS antenna.Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4023-020108 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GPS antenna.

Requirement. N/A

Performance Standard. Without supervision, install GPS antenna.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4024-020111 [Y] N/A N/A B N/A A N/A Times: 1

Task. Air vehicle communications fault isolation.

Requirement. N/A

Performance Standard. Without supervision, perform air vehicle communications fault isolation.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4025-020111 [Y] N/A N/A B N/A A N/A Times: 1

Task. Air vehicle avionics fault isolation.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. Without supervision, perform air vehicle avionics fault isolation.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-4026-020110 [L] N/A N/A B N/A A N/A Times: 1

Task. Set video signal frequency.

Requirement. N/A

Performance Standard. Without supervision, perform setting of video signal frequency.

Prerequisites. Complete level 3000 AVIS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

AVIS-6001-020111 [N/A] N/A N/A B N/A A N/A Times: 1

Task. Complete levels 1000 through 4000 AVIS tasks.

Requirement. N/A

Performance Standard. Complete levels 1000 through 4000 AVIS tasks.

Prerequisites. Complete level 4000 INSP tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.9 PLUG IN OPTRONIC PAYLOAD SYSTEM (POP). The Plug In Optronic Payload

15 Jun 12

System (030) tasks provide the required knowledge to perform all aspects of maintenance on the POP-300 Payload as it pertains to the individual's MOS. Upon completion of the POP System tasks, level 2000-4000, the individual shall be certified as POP SSP. An individual that is POP SSP Certified has the ability to act as the supervising authority of a task.

Table 2-09. Maintenance System "Plug In Optronics Payload" (POP)

Maintenance Systems					
Plug In Optronic Payload System (POP)					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2005	3001-3005	4001-4005	N/A	6001

NOTE

For task header description see Appendix A

POPS-2001-020101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove POP payload.

Requirement. N/A

Performance Standard. With supervision, remove POP payload.

Prerequisites. Complete level 1000 POPS tasks..

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-2002-020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install POP payload.

Requirement. N/A

Performance Standard. With supervision,remove POP payload.

Prerequisites. Complete level 1000 POPS tasks..

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-2003-020101 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform POP payload functional test.

Requirement. N/A

Performance Standard. With supervision, perform POP payload functional test.

Prerequisites. Complete level 1000 POPS tasks..

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-2004-020101 [Y] N/A N/A B N/A A N/A Times: 1

Task. Troubleshoot the POP payload.

Requirement. N/A

Performance Standard. With supervision, troubleshoot the POP payload.

Prerequisites. Complete level 1000 POPS tasks..

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-2005-020101 [G] N/A N/A B N/A A N/A Times: 1

Task. POP payload window/lens cleaning.

Requirement. N/A

Performance Standard. With supervision, perform POP payload window/lens cleaning.

Prerequisites. Complete level 1000 POPS tasks..

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-3001-020101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove POP payload.

Requirement. N/A

Performance Standard. With supervision, remove POP payload.

Prerequisites. Complete level 2000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-3002-020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install POP payload.

Requirement. N/A

Performance Standard. With supervision, install POP payload.

Prerequisites. Complete level 2000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-3003-020101 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform POP payload functional test.

Requirement. N/A

Performance Standard. With supervision, perform POP payload functional test.

Prerequisites. Complete level 2000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

NAVMC 4790.02

15 Jun 12

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-3004-020101 [Y] N/A N/A B N/A A N/A Times: 1

Task. Troubleshoot the POP payload.

Requirement. N/A

Performance Standard. With supervision, troubleshoot the POP payload.

Prerequisites. Complete level 2000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-3005-020101 [G] N/A N/A B N/A A N/A Times: 1

Task. Perform POP payload window/lens cleaning.

Requirement. N/A

Performance Standard. With supervision, perform POP payload window/lens cleaning.

Prerequisites. Complete level 2000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-4001-020101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove POP payload.

Requirement. N/A

Performance Standard. Without supervision, remove POP payload.

Prerequisites. Complete level 3000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-4002-020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install POP payload

Requirement. N/A

Performance Standard. Without supervision, install POP payload.

Prerequisites. Complete level 3000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-4003-020101 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform POP payload functional test.

Requirement. N/A

Performance Standard. Without supervision, perform POP payload functional test.

Prerequisites. Complete level 3000 POPS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-4004-020101 [Y] N/A N/A B N/A A N/A Times: 1

Task. Troubleshoot the POP payload.

Requirement. N/A

Performance Standard. Without supervision, troubleshoot the POP payload.

15 Jun 12

Prerequisites. Complete level 3000 POPS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-4005-020101	[G]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform POP payload window/lens cleaning.Requirement. N/APerformance Standard. Without supervision, perform POP payload window/lens cleaning.Prerequisites. Complete level 3000 POPS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

POPS-6001-020101	[N/A]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-------	-----	-----	---	-----	---	-----	----------

Task. Complete level 1000 through 4000 POPS tasks.Requirement. N/APerformance Standard. Complete level 1000 through 4000 POPS tasks.Prerequisites. Complete level 4000 POPS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.10 GROUND CONTROL STATION/GROUND DATA TERMINAL SYSTEM (GCS/GDT). The Ground Control Station/Ground Data Terminal System (GCS/GDT) tasks provide the required knowledge to perform all aspects of maintenance on the Ground

15 Jun 12

Control Station and Ground Data Terminal as it pertains to the individual's MOS. Upon completion of the GCS/GDT System tasks, level 2000-4000, the individual shall be certified as GCS/GDT SSP. An individual that is GCS/GDT SSP Certified has the ability to act as the supervising authority of a task.

Table 2-10. Maintenance System "Ground Control Station/Ground Data Terminal" (GCS/GDT)

<i>Maintenance Systems</i>					
<i>Ground Control Station/Ground Data Terminal System (GCS/GDT)</i>					
<i>INDOC</i>	<i>BASIC</i>	<i>INTERMEDIATE</i>	<i>ADVANCE</i>	<i>MGMT</i>	<i>QDL</i>
N/A	2001-2076	3001-3075	4001-4076	N/A	6001

NOTE

For task header description see Appendix A

GCSS-2001-8303 [G] N/A N/A B N/A A N/A Times: 1

Task. Maintain cleanliness of the GCS/GDT.

Requirement. N/A

Performance Standard. With supervision, maintain cleanliness of the GCS/GDT.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2002-830301 [E] N/A N/A B N/A A N/A Times: 1

Task. GCS/GDT power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform GCS/GDT power up/power down procedures.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2003-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove flat panel display (FPD).

Requirement. N/A

Performance Standard. With supervision, remove flat panel display (FPD).

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2004-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install flat panel display (FPD).

Requirement. N/A

Performance Standard. With supervision, install flat panel display (FPD).

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2005-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove keyboards/trackball.

Requirement. N/A

Performance Standard. With supervision, remove keyboards/trackball.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2006-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install keyboards/trackball.

Requirement. N/A

Performance Standard. With supervision, install keyboards/trackball.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2007-830306 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove uninterrupted power supply (UPS) #1 and #2.

Requirement. N/A

Performance Standard. With supervision, remove uninterrupted power supply (UPS) #1 and #2.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2008-830306 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install Uninterrupted Power Supply (UPS) #1 and #2.

Requirement. N/A

Performance Standard. With supervision, install uninterrupted power supply (UPS) #1 and #2.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2009-830303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove 9" monitor.

Requirement. N/A

Performance Standard. With supervision, remove 9" monitor.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2010-830303 [Q] N/A N/A B N/A A N/A N/A Times: 1

Task. Install 9" monitor.

Requirement. N/A

Performance Standard. With supervision, install 9" monitor.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2011-830302 [P] N/A N/A B N/A A N/A N/A Times: 1

Task. Remove versa module eurobus (VME).

Requirement. N/A

Performance Standard. With supervision, remove versa module eurobus (VME).

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2012-830302 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install versa module eurobus (VME).

Requirement. N/A

Performance Standard. With supervision, install versa module eurobus (VME).

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2013-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove DVD recorder.

Requirement. N/A

Performance Standard. With supervision, remove DVD recorder.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2014-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install DVD recorder.

NAVMC 4790.02

15 Jun 12

Requirement. N/A

Performance Standard. With supervision, install DVD recorder.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2015-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove Chroma Keyer.

Requirement. N/A

Performance Standard. With supervision, remove chroma keyer.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2016-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install chroma keyer.

Requirement. N/A

Performance Standard. With supervision, install chroma keyer.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2017-830305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove Communications System Control.

Requirement. N/A

Performance Standard. With supervision, remove communications system control.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2018-83030502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install Communications System Control.

Requirement. N/A

Performance Standard. With supervision, install communications system control.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2019-83030109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove Foot Switch.

Requirement. N/A

Performance Standard. With supervision, remove foot switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2020-83030109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install foot switch.

Requirement. N/A

Performance Standard. With supervision, install foot switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2021-8303010401 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove joystick/power switch.

Requirement. N/A

Performance Standard. With supervision, remove joystick/power switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2022-83030104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install Joystick/Power Switch.

Requirement. N/A

Performance Standard. With supervision, install joystick/power switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2023-83030503 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove junction box push to talk.

Requirement. N/A

Performance Standard. With supervision, remove junction box push to talk.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2024-83030503 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install junction box push to talk.

Requirement. N/A

Performance Standard. With supervision, install junction box push to talk.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2025-83030108 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove thermal printer.

Requirement. N/A

Performance Standard. With supervision, remove thermal printer.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2026-83030108 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install thermal printer.

Requirement. N/A

Performance Standard. With supervision, install thermal printer

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2027-83030106 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove time code generator.

Requirement. N/A

Performance Standard. With supervision, remove time code generator.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2028-83030106 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install time code generator.

Requirement. N/A

Performance Standard. With supervision, install time code generator.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2029-83030305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove closed caption encoder.

Requirement. N/A

Performance Standard. With supervision, remove closed caption encoder.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2030-83030305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install closed caption encoder.

Requirement. N/A

Performance Standard. With supervision, install closed caption encoder.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2031-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove embedded trainer PC 1 & 2.

Requirement. N/A

Performance Standard. With supervision, remove embedded trainer PC 1 & 2.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2032-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install embedded trainer PC 1 & 2.

Requirement. N/A

Performance Standard. With supervision, install embedded trainer PC 1& 2.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2033-83030102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove flat screen monitor and keyboard.

Requirement. N/A

Performance Standard. With supervision, remove flat screen monitor and keyboard.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2034-83030102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install flat screen monitor and keyboard.

Requirement. N/A

Performance Standard. With supervision, install flat screen monitor and keyboard.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2035-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove Storage Drawer.

Requirement. N/A

Performance Standard. With supervision, remove storage drawer.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2036-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install storage drawer.

Requirement. N/A

Performance Standard. With supervision, install storage drawer.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2037-83030304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove RGB distribution amplifier.

Requirement. N/A

Performance Standard. With supervision, remove RGB Distribution

NAVMC 4790.02

15 Jun 12

Amplifier.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2038-83030304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install RGB distribution amplifier.

Requirement. N/A

Performance Standard. With supervision, install RGB distribution amplifier.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics:

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2039-83030307 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove telemetry switch.

Requirement. N/A

Performance Standard. With supervision, remove telemetry switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2040-83030307 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install telemetry switch.

Requirement. N/A

Performance Standard. With supervision, install telemetry switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2041-83030603 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UPS Controller.

Requirement. N/A

Performance Standard. With supervision, remove UPS controller.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2042-83030603 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UPS controller.

Requirement. N/A

Performance Standard. With supervision, install UPS Controller.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

Task. Remove video switch.

Requirement. N/A

Performance Standard. With supervision, remove video switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

Task. Install video switch.

Requirement. N/A

Performance Standard. With supervision, install video switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

Task. Remove 28 volt power supply.

Requirement. N/A

Performance Standard. With supervision, remove 28 volt power supply.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2046-83030604 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install 28 volt power supply.

Requirement. N/A

Performance Standard. With supervision, install 28 volt power supply.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2047-83030705 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove keyboard video mouse (KVM) switch.

Requirement. N/A

Performance Standard. With supervision, remove keyboard video mouse (KVM) switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

TMJs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2048-83030705 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install keyboard video mouse (KVM) switch.

Requirement. N/A

Performance Standard. With supervision, install keyboard video mouse (KVM) switch.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2049-8303	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove air conditioning unit.Requirement. N/APerformance Standard. With supervision, remove air conditioning unit.Prerequisites. Complete level 1000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2050-8303	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install air conditioning unit.Requirement. N/APerformance Standard. With supervision, install air conditioning unit.Prerequisites. Complete level 1000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2051-830301	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove remote monitoring device.Requirement. N/APerformance Standard. With supervision, remove remote monitoring device.Prerequisites. Complete level 1000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2052-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install remote monitoring device.

Requirement. N/A

Performance Standard. With supervision, install remote monitoring device.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2053-83050101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove data link interface box (DIB) battery.

Requirement. N/A

Performance Standard. With supervision, remove data link interface box (DIB) battery.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2054-83050101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install data link interface box (DIB) battery.

Requirement. N/A

Performance Standard. With supervision, install data link interface box (DIB) battery.

Prerequisites. Complete level 1000 GCSS tasks.

NAVMC 4790.02

15 Jun 12

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2055-83050102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove DIB fan assembly.

Requirement. N/A

Performance Standard. With supervision, remove DIB fan assembly.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2056-83050102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install DIB fan assembly.

Requirement. N/A

Performance Standard. With supervision, install DIB fan assembly.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2057-830506 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT tripod.

Requirement. N/A

Performance Standard. With supervision, remove GDT tripod.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2058-830506 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT tripod.

Requirement. N/A

Performance Standard. With supervision, install GDT tripod.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2059-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT pedestal.

Requirement. N/A

Performance Standard. With supervision, remove GDT pedestal.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2060-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT pedestal.

Requirement. N/A

Performance Standard. With supervision, install GDT pedestal.

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2061-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT dish antenna.

Requirement. N/A

Performance Standard. With supervision, remove GDT Dish Antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2062-830504 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT dish antenna.

Requirement. N/A

Performance Standard. With supervision, install GDT dish antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2063-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT feed horn antenna.

Requirement. N/A

Performance Standard. With supervision, remove GDT feed horn antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2064-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT feed horn antenna.

Requirement. N/A

Performance Standard. With supervision, install GDT feed horn antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2065-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove primary omni antenna.

Requirement. N/A

Performance Standard. With supervision, remove primary omni antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2066-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install primary omni antenna.

NAVMC 4790.02

15 Jun 12

Requirement. N/A

Performance Standard. With supervision, install primary omni antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2067-830508 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UHF/GPS tripod.

Requirement. N/A

Performance Standard. With supervision, remove UHF/GPS tripod.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2068-830508 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UHF/GPS tripod.

Requirement. N/A

Performance Standard. With supervision, install UHF/GPS tripod.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2069-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GPS antenna.

Requirement. N/A

Performance Standard. With supervision, remove GPS antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2070-830504 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GPS antenna.

Requirement. N/A

Performance Standard. With supervision, install GPS antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2071-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UHF antenna.

Requirement. N/A

Performance Standard. With supervision, remove UHF antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

NAVMC 4790.02

15 Jun 12

GCSS-2072-830502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UHF antenna.

Requirement. N/A

Performance Standard. With supervision, install UHF antenna.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2073-830502 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform tactical quiet generator (TQG) operation.

Requirement. N/A

Performance Standard. With supervision, perform tactical quiet generator (TQG) operation.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7BA-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2074-830502 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform tactical quiet generator(TQG) power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform tactical quiet generator (TQG) power up/power down procedures.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2075-830301 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform GCS fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform GCS fault isolation.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-2076-83030306 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform fiber optic fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform fiber optic fault isolation.

Prerequisites. Complete level 1000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3001-8303 [G] N/A N/A B N/A A N/A Times: 1

Task. Maintain cleanliness of the GCS/GDT.

Requirement. N/A

Performance Standard. With supervision, maintain cleanliness of the GCS/GDT.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

NAVMC 4790.02

15 Jun 12

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3002-830301 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform GCS/GDT power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform GCS/GDT power up/power down procedures.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3003-83030102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove flat panel display (FPD).

Requirement. N/A

Performance Standard. With supervision, remove flat panel display (FPD).

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3004-83030102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install flat panel display (FPD).

Requirement. N/A

Performance Standard. With supervision, install flat panel display (FPD).

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3005-83030103 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove keyboards/trackball.

Requirement. N/A

Performance Standard. With supervision, remove keyboards/trackball.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3006-83030103 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install keyboards/trackball.

Requirement. N/A

Performance Standard. With supervision, install keyboards/trackball.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3007-83030602 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove uninterrupted power supply (UPS) #1 and #2.

Requirement. N/A

Performance Standard. With supervision, remove uninterrupted power supply (UPS) #1 and #2.

15 Jun 12

Prerequisites. Complete level 2000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3008-83030602	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install uninterrupted power supply (UPS) #1 and #2.Requirement. N/APerformance Standard. With supervision, install uninterrupted power supply (UPS) #1 and #2.Prerequisites. Complete level 2000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3009-83030302	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove 9" monitor.Requirement. N/APerformance Standard. With supervision, remove 9" monitor.Prerequisites. Complete level 2000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3010-83030302	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install 9" monitor.

Requirement. N/A

Performance Standard. With supervision, install 9" monitor.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3011-83030201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove versa module eurobus (VME).

Requirement. N/A

Performance Standard. With supervision, remove versa module eurobus (VME).

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3012-83030201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install versa module eurobus (VME).

Requirement. N/A

Performance Standard. With supervision, install versa module eurobus (VME).

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

NAVMC 4790.02
15 Jun 12
GCSS-3013-83030111 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove DVD recorder.

Requirement. N/A

Performance Standard. With supervision, remove DVD recorder.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3014-83030111 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install DVD recorder.

Requirement. N/A

Performance Standard. With supervision, install DVD recorder.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3015-83030107 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove chroma keyer.

Requirement. N/A

Performance Standard. With supervision, remove chroma keyer.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3016-83030107 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install chroma keyer.

Requirement. N/A

Performance Standard. With supervision, install chroma keyer.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3017-83030502 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove communications system control.

Requirement. N/A

Performance Standard. With supervision, remove communications system control.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3018-83030502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install communications system control.

Requirement. N/A

Performance Standard. With supervision, install communications system control.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

NAVMC 4790.02

15 Jun 12

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3019-83030109 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove foot switch.

Requirement. N/A

Performance Standard. With supervision, remove foot switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3020-83030109 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install foot switch.

Requirement. N/A

Performance Standard. With supervision, install foot switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3021-8303010401 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove joystick/power switch.

Requirement. N/A

Performance Standard. With supervision, remove joystick/power switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3022-8303010401 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install joystick/power switch.

Requirement. N/A

Performance Standard. With supervision, install joystick/power switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3023-83030503 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove junction box push to talk.

Requirement. N/A

Performance Standard. With supervision, remove junction box push to talk.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3024-83030503 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install junction box push to talk.

Requirement. N/A

Performance Standard. With supervision, install junction box push to talk.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3025-83030108 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove thermal printer.

Requirement. N/A

Performance Standard. With supervision, remove thermal printer.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3026-83030108 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install thermal printer.

Requirement. N/A

Performance Standard. With supervision, install thermal printer.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3027-83030106 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove time code generator.

Requirement. N/A

Performance Standard. With supervision, remove time code generator.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3028-83030106 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install time code generator.

Requirement. N/A

Performance Standard. With supervision, install time code generator.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3029-83030305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove closed caption encoder.

Requirement. N/A

Performance Standard. With supervision, remove closed caption encoder.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3030-83030305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install closed caption encoder.

Requirement. N/A

15 Jun 12

Performance Standard. With supervision, install closed caption encoder.Prerequisites. Complete level 2000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3031-830301	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove embedded trainer PC #1 and #2.Requirement. N/APerformance Standard. With supervision, remove embedded trainer PC #1 and #2.Prerequisites. Complete level 2000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3032-830301	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install embedded trainer PC #1 and #2.Requirement. N/APerformance Standard. With supervision, install embedded trainer PC #1 and #2.Prerequisites. Complete level 2000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3033-83030102	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove flat screen monitor and keyboard.

Requirement. N/A

Performance Standard. With supervision, remove flat screen monitor and keyboard.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3034-83030102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install flat screen monitor and keyboard.

Requirement. N/A

Performance Standard. With supervision, install flat screen monitor and keyboard.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3035-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove storage drawer.

Requirement. N/A

Performance Standard. With supervision, remove storage drawer.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3036-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install storage drawer.

Requirement. N/A

Performance Standard. With supervision, install storage drawer.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3037-83030304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove RGB distribution amplifier.

Requirement. N/A

Performance Standard. With supervision, remove RGB distribution amplifier.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3038-83030304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install RGB distribution amplifier.

Requirement. N/A

Performance Standard. With supervision, install RGB distribution amplifier.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3039-83030307 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove telemetry switch.

Requirement. N/A

Performance Standard. With supervision, remove telemetry switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3040-83030307 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install telemetry switch.

Requirement. N/A

Performance Standard. With supervision, install telemetry switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3041-83030603 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UPS Controller.

Requirement. N/A

Performance Standard. With supervision, remove UPS controller.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3042-83030603 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UPS Controller.

Requirement. N/A

Performance Standard. With supervision, install UPS controller.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3043-83030303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove video switch.

Requirement. N/A

Performance Standard. With supervision, remove video switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3044-83030303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install video switch.

Requirement. N/A

Performance Standard. With supervision, install video switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. Complete level 2000 GCSS tasks.

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3045-83030604 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove 28 Volt Power Supply.

Requirement. N/A

Performance Standard. With supervision, remove 28 volt power supply.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3045-83030604 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install 28 volt power supply.

Requirement. N/A

Performance Standard. With supervision, install 28 volt power supply.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support.

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3046-83030705 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove keyboard video mouse (KVM) switch.

Requirement. N/A

Performance Standard. With supervision, remove keyboard video mouse (KVM) switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3047-83030705 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install keyboard video mouse (KVM) switch.

Requirement. N/A

Performance Standard. With supervision, install keyboard video mouse (KVM) switch.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3048-8303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air conditioning unit.

Requirement. N/A

Performance Standard. With supervision, remove air conditioning unit.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3049-8303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air conditioning unit.

Requirement. N/A

Performance Standard. With supervision, install air conditioning unit.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3050-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove remote monitoring device.

Requirement. N/A

Performance Standard. With supervision, remove remote monitoring device.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3051-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install remote monitoring device.

Requirement. N/A

Performance Standard. With supervision, install remote monitoring device.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3052-83050101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove data link interface box (DIB) battery.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. With supervision, remove data link interface box (DIB) battery.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3053-83050101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install data link interface box (DIB) battery.

Requirement. N/A

Performance Standard. With supervision, install data link interface box (DIB) battery.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3054-83050102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove DIB fan assembly.

Requirement. N/A

Performance Standard. With supervision, remove DIB fan assembly.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3055-83050102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install DIB Fan Assembly.

Requirement. N/A

Performance Standard. With supervision, Install DIB Fan Assembly.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3056-830506 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT tripod.

Requirement. N/A

Performance Standard. With supervision, remove GDT tripod.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3057-830506 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT tripod.

Requirement. N/A

Performance Standard. With supervision, install GDT tripod.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

NAVMC 4790.02

15 Jun 12

GCSS-3058-8305

[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----	-----	-----	---	-----	---	-----	----------

Task. Remove GDT pedestal.

Requirement. N/A

Performance Standard. With supervision, remove GDT pedestal.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3059-8305

[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----	-----	-----	---	-----	---	-----	----------

Task. Install GDT pedestal.

Requirement. N/A

Performance Standard. With supervision, install GDT pedestal.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3060-830504

[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
-----	-----	-----	---	-----	---	-----	----------

Task. Remove GDT dish antenna.

Requirement. N/A

Performance Standard. With supervision, remove GDT dish antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3061-830504 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT dish antenna.

Requirement. N/A

Performance Standard. With supervision, install GDT dish antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3062-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT feed horn antenna.

Requirement. N/A

Performance Standard. With supervision, remove GDT feed horn antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3063-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT feed horn antenna.

Requirement. N/A

Performance Standard. With supervision, install GDT feed horn antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3064-8305	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove primary omni antenna.

Requirement. N/A

Performance Standard. With supervision, remove primary omni antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3065-8305	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install primary omni antenna.

Requirement. N/A

Performance Standard. With supervision, install primary omni antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3066-830508	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove UHF/GPS tripod.

Requirement. N/A

Performance Standard. With supervision, remove UHF/GPS tripod.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3067-830508 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UHF/GPS tripod.

Requirement. N/A

Performance Standard. With supervision, install UHF/GPS tripod.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3068-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GPS antenna.

Requirement. N/A

Performance Standard. With supervision, remove GPS antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3069-830504 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GPS antenna.

Requirement. N/A

Performance Standard. With supervision, install GPS antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3070-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UHF antenna.

Requirement. N/A

Performance Standard. With supervision, remove UHF antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3071-830502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UHF antenna.

Requirement. N/A

Performance Standard. With supervision, install UHF antenna.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3072-830502 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform tactical quiet generator (TQG) operation.

Requirement. N/A

Performance Standard. With supervision, perform tactical quiet generator (TQG) operation.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7BA-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3073-830502 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform tactical quiet generator(TQG) power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform tactical quiet generator(TQG) power up/power down procedures.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3074-830301 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform GCS fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform GCS fault isolation.

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-3075-83030306 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform fiber optic fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform fiber optic fault isolation.

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 2000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4001-8303 [G] N/A N/A B N/A A N/A Times: 1

Task. Maintain cleanliness of the GCS/GDT.

Requirement. N/A

Performance Standard. Without supervision, maintain cleanliness of the GCS/GDT.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4002-830301 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform GCS/GDT power up/power down procedures.

Requirement. N/A

Performance Standard. Without supervision, perform GCS/GDT power up/power down procedures.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4003-83030102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove flat panel display (FPD).

Requirement. N/A

Performance Standard. Without supervision, remove flat panel display (FPD).

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4004-83030102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install flat panel display (FPD).

Requirement. N/A

Performance Standard. Without supervision, install flat panel display (FPD).

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4005-83030103 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove keyboards/trackball.

Requirement. N/A

Performance Standard. Without supervision, remove keyboards/trackball.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

GCSS-4006-83030103 [Q] N/A N/A B N/A A N/A Times: 1Task. Install keyboards/trackball.Requirement. N/APerformance Standard. Without supervision, install keyboards/trackball.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-4007-83030602 [P] N/A N/A B N/A A N/A Times: 1Task. Remove uninterrupted power supply (UPS) #1 and #2.Requirement. N/APerformance Standard. Without supervision, remove uninterrupted power supply (UPS) #1 and #2.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-4008-83030602 [Q] N/A N/A B N/A A N/A Times: 1Task. Install uninterrupted power supply (UPS) #1 and #2.Requirement. N/APerformance Standard. Without supervision, install uninterrupted power supply (UPS) #1 and #2.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4009-83030302	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove 9" monitor.

Requirement. N/A

Performance Standard. Without supervision, remove 9" monitor.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4010-83030302	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install 9" monitor.

Requirement. N/A

Performance Standard. Without supervision, install 9" monitor.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4011-83030201	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove versa module eurobus (VME).

Requirement. N/A

Performance Standard. Without supervision, remove versa module eurobus (VME).

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4012-83030201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install versa module eurobus (VME).

Requirement. N/A

Performance Standard. Without supervision, install versa module eurobus (VME).

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4013-83030111 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove DVD recorder.

Requirement. N/A

Performance Standard. Without supervision, remove DVD recorder.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4014-83030111 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install DVD recorder.

Requirement. N/A

Performance Standard. Without supervision, install DVD recorder.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4015-83030107 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove chroma keyer.

Requirement. N/A

Performance Standard. Without supervision, remove chroma keyer.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4016-83030107 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install chroma keyer.

Requirement. N/A

Performance Standard. Without supervision, install chroma keyer.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4017-83030502 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove communications system control.

Requirement. N/A

Performance Standard. Without supervision, remove communications system control.

Prerequisites. Complete level 3000 GCSS tasks.

15 Jun 12

External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDOAR, 6314 MOS QAR

GCSS-4018-83030502	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install communications system control.Requirement. N/APerformance Standard. Without supervision, install communications system control.Prerequisites. Complete level 3000 GCSS tasks. . . .External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDOAR, 6314 MOS QAR

GCSS-4019-83030109	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove foot switch.Requirement. N/APerformance Standard. Without supervision, remove foot switch.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDOAR, 6314 MOS QAR

GCSS-4020-83030109	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install foot switch.Requirement. N/A

Performance Standard. Without supervision, install foot switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4021-8303010401 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove joystick/power switch.

Requirement. N/A

Performance Standard. Without supervision, remove joystick/power switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4022-83030104 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install joystick/power switch.

Requirement. Complete level 3000 GCSS tasks.

Performance Standard. Without supervision, install joystick/power switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4023-83030503 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove junction box push to talk.

15 Jun 12

Requirement. N/APerformance Standard. Without supervision, remove junction box push to talk.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-4024-83030503 [Q] N/A N/A B N/A A N/A Times: 1Task. Install junction box push to talk.Requirement. N/APerformance Standard. Without supervision, install junction box push to talk.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-4025-83030108 [P] N/A N/A B N/A A N/A Times: 1Task. Remove thermal printer.Requirement. N/APerformance Standard. Without supervision, remove thermal printer.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

15 Jun 12

GCSS-4026-83030108	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install thermal printer.

Requirement. N/A

Performance Standard. Without supervision, install thermal printer.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4027-83030106	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove time code generator.

Requirement. N/A

Performance Standard. Without supervision, remove time code generator.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4028-83030106	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install time code generator.

Requirement. N/A

Performance Standard. Without supervision, install time code generator.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4029-83030305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove closed caption encoder.

Requirement. N/A

Performance Standard. Without supervision, remove closed caption encoder.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4030-83030305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install closed caption encoder.

Requirement. N/A

Performance Standard. Without supervision, install closed caption encoder.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4031-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove embedded trainer PC #1 and #2.

Requirement. N/A

Performance Standard. Without supervision, remove embedded trainer PC #1 and #2.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4032-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install embedded trainer PC #1 and #2.

Requirement. N/A

Performance Standard. Without supervision, install embedded trainer PC #1 and #2.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4033-83030102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove flat screen monitor and keyboard.

Requirement. N/A

Performance Standard. Without supervision, remove flat screen monitor and keyboard.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4034-83030102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install flat screen monitor and keyboard.

Requirement. N/A

Performance Standard. Without supervision, install flat screen monitor and keyboard.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4035-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove storage drawer.

Requirement. N/A

Performance Standard. Without supervision, remove storage drawer.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4036-830301 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install storage drawer.

Requirement. N/A

Performance Standard. Without supervision, install storage drawer.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4037-83030304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove RGB distribution amplifier.

Requirement. N/A

Performance Standard. Without supervision, remove RGB distribution amplifier.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4038-83030304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install RGB distribution amplifier.

Requirement. N/A

Performance Standard. Without supervision, install RGB distribution amplifier.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4039-83030307 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove telemetry switch.

Requirement. N/A

Performance Standard. Without supervision, remove telemetry switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4040-83030307 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install telemetry switch.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. Without supervision, install telemetry switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4041-83030603 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UPS controller.

Requirement. N/A

Performance Standard. Without supervision, remove UPS controller.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4042-83030603 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UPS Controller.

Requirement. N/A

Performance Standard. Without supervision, install UPS controller.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4043-83030303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove video switch.

Requirement. N/A

Performance Standard. Without supervision, remove video switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4044-83030303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install video switch.

Requirement. N/A

Performance Standard. Without supervision, install video switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4045-83030604 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove 28 volt power supply.

Requirement. N/A

Performance Standard. Without supervision, remove 28 volt power supply.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4046-83030604 [Q] N/A N/A B N/A A N/A Times: 1

NAVMC 4790.02

15 Jun 12

Task. Install 28 volt power supply.

Requirement. N/A

Performance Standard. Without supervision, install 28 volt power supply.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4047-83030705 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove keyboard video mouse (KVM) switch.

Requirement. N/A

Performance Standard. Without supervision, remove keyboard video mouse (KVM) switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4048-83030705 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install keyboard video mouse (KVM) switch.

Requirement. N/A

Performance Standard. Without supervision, install keyboard video mouse (KVM) switch.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4049-8303 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove air conditioning unit.

Requirement. N/A

Performance Standard. Without supervision, remove air conditioning unit.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4050-8303 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install air conditioning unit.

Requirement. N/A

Performance Standard. Without supervision, install air conditioning unit.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4051-830301 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove remote monitoring device.

Requirement. N/A

Performance Standard. Without supervision, remove remote monitoring device.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4052-830301	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install remote monitoring device.Requirement. N/APerformance Standard. Without supervision, install remote monitoring device.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4053-83050101	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove data link interface box (DIB) battery.Requirement. N/APerformance Standard. Without supervision, remove data link interface box (DIB) battery.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4054-83050101	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
--------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install data link interface box (DIB) battery.Requirement. N/APerformance Standard. Without supervision, install data link interface box (DIB) battery.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4055-83050102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove DIB fan assembly.

Requirement. N/A

Performance Standard. Without supervision, remove DIB fan assembly.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4056-83050102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install DIB fan assembly.

Requirement. N/A

Performance Standard. Without supervision, install DIB fan assembly.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4057-830506 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT tripod.

Requirement. N/A

Performance Standard. Without supervision, remove GDT tripod.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

NAVMC 4790.02

15 Jun 12

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4058-830506 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT tripod.

Requirement. N/A

Performance Standard. Without supervision, install GDT tripod.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4059-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT pedestal.

Requirement. N/A

Performance Standard. Without supervision, remove GDT pedestal.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4060-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT pedestal.

Requirement. N/A

Performance Standard. Without supervision, install GDT pedestal.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4061-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT dish antenna.

Requirement. N/A

Performance Standard. Without supervision, remove GDT dish antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4062-830504 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT dish antenna.

Requirement. N/A

Performance Standard. Without supervision, install GDT dish antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4063-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove GDT feed horn antenna.

Requirement. N/A

Performance Standard. Without supervision, remove GDT feed horn antenna.

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4064-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GDT feed horn antenna.

Requirement. N/A

Performance Standard. Without supervision, install GDT feed horn antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4065-8305 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove primary omni antenna.

Requirement. N/A

Performance Standard. Without supervision, remove primary omni antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4066-8305 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install primary omni antenna.

Requirement. N/A

15 Jun 12

Performance Standard. Without supervision, install primary omni antenna.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4067-830508	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove UHF/GPS tripod.Requirement. N/APerformance Standard. Without supervision, remove UHF/GPS tripod.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4068-830508	[Q]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Install UHF/GPS tripod.Requirement. N/APerformance Standard. Without supervision, install UHF/GPS tripod.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4069-830504	[P]	N/A	N/A	B	N/A	A	N/A	Times: 1
------------------	-----	-----	-----	---	-----	---	-----	----------

Task. Remove GPS antenna.

NAVMC 4790.02

15 Jun 12

Requirement. N/A

Performance Standard. Without supervision, remove GPS antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4070-830504 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install GPS antenna.

Requirement. N/A

Performance Standard. Without supervision, install GPS antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4071-830504 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UHF antenna.

Requirement. N/A

Performance Standard. Without supervision, remove UHF antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4072-830502 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UHF Antenna.

Requirement. N/A

Performance Standard. Without supervision, install UHF antenna.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4073-830502 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform tactical quiet generator (TQG) operation.

Requirement. N/A

Performance Standard. Without supervision, perform tactical quiet generator (TQG) operation.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7BA-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

GCSS-4074-830502 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform tactical quiet generator(TQG) power up/power down procedures.

Requirement. N/A

Performance Standard. Without supervision, perform(TQG) power up/power down procedures.

Prerequisites. Complete level 3000 GCSS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-4075-830301 [Y] N/A N/A B N/A A N/A Times: 1Task. Perform GCS fault isolation.Requirement. N/APerformance Standard. Without supervision, perform GCS fault isolation.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-4076-83030306 [Y] N/A N/A B N/A A N/A Times: 1Task. Perform fiber optic fault isolation.Requirement. N/APerformance Standard. Without supervision, perform fiber optic fault isolation.Prerequisites. Complete level 3000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARGCSS-6001-8303 [N/A] N/A N/A B N/A A N/A Times: 1Task. Complete level 2000 through 4000 GCSS tasks.Requirement. N/APerformance Standard. Complete level 2000 through 4000 GCSS tasks.Prerequisites. Complete level 4000 GCSS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.11 PORTABLE GROUND CONTROL STATION(PGCS) /PORTABLE GROUND DATA TERMINAL (PGDT) SYSTEM. The Portable Ground Control System (PGCS) tasks provide the required knowledge to perform all aspects of maintenance on the Portable Ground Control Station (PGCS) as it pertains to the individual's MOS. Upon completion of the PGCS System tasks, level 2000-4000, the individual shall be certified as PGCS SSP. An individual that is PGCS SSP Certified has the ability to act as the supervising authority of a task.

Table 2-11. Maint System "Portable Ground Control Station" (PGCS)

Maintenance Systems					
Portable Ground Control Station System (PGCS)					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2014	3001-3014	4001-4014	N/A	6001

NOTE

For task header description see Appendix A

PGCS-2001-8304 [G] N/A N/A B N/A A N/A Times: 1

Task. Maintain cleanliness of the PGCS/PGDT.

Requirement. N/A

Performance Standard. With supervision, maintain cleanliness of the PGCS/PGDT.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2002-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform PGCS/PGDT power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform PGCS/PGDT power up/power down procedures.

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2003-830405 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove RF box.

Requirement. N/A

Performance Standard. With supervision, remove RF box.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2004-830405 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install RF box.

Requirement. N/A

Performance Standard. With supervision, install RF box.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2005-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT tripod.

Requirement. N/A

Performance Standard. With supervision, remove PGDT tripod.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2006-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT tripod.

Requirement. N/A

Performance Standard. With supervision, install PGDT tripod.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2007-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT primary antenna.

Requirement. N/A

Performance Standard. With supervision, remove PGDT primary antenna.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2008-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT primary antenna.

NAVMC 4790.02

15 Jun 12

Requirement. N/A

Performance Standard. With supervision, install PGDT primary antenna.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2009-830402 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT secondary antenna.

Requirement. N/A

Performance Standard. With supervision, remove PGDT secondary antenna.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2010-830402 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT secondary antenna.

Requirement. N/A

Performance Standard. With supervision, install PGDT secondary antenna.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2011-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UPS.

Requirement. N/A

Performance Standard. With supervision, remove UPS.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2012-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UPS.

Requirement. N/A

Performance Standard. With supervision, install UPS.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-2013-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform 2KW generator operation.

Requirement. N/A

Performance Standard. With supervision, perform 2KW generator operation.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7BA-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

Task. Perform 2KW generator servicing procedures.

Requirement. N/A

Performance Standard. With supervision, perform 2KW generator servicing procedures.

Prerequisites. Complete level 1000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

Task. Maintain cleanliness of the PGCS/PGDT.

Requirement. N/A

Performance Standard. With supervision, maintain cleanliness of the PGCS/PGDT.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

Task. Perform PGCS/PGDT power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform PGCS/PGDT power up/power down procedures.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3003-830405 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove RF box.

Requirement. N/A

Performance Standard. With supervision, remove RF box.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3004-830405 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install RF box.

Requirement. N/A

Performance Standard. With supervision, install RF box.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3005-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT tripod.

Requirement. N/A

Performance Standard. With supervision, remove PGDT tripod.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3006-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT tripod.

Requirement. N/A

Performance Standard. With supervision, install PGDT tripod.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3007-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT primary antenna.

Requirement. N/A

Performance Standard. With supervision, remove PGDT primary antenna.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3008-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT primary antenna.

Requirement. N/A

Performance Standard. With supervision, install PGDT primary antenna.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3009-830402 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT secondary antenna.

Requirement. N/A

Performance Standard. With supervision, remove PGDT secondary antenna.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3010-830402 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT secondary antenna.

Requirement. N/A

Performance Standard. With supervision, install PGDT secondary antenna.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3011-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UPS.

Requirement. N/A

Performance Standard. With supervision, remove UPS.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

NAVMC 4790.02

15 Jun 12

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3012-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UPS.

Requirement. N/A

Performance Standard. With supervision, install UPS.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3013-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform 2KW generator operation.

Requirement. N/A

Performance Standard. With supervision, perform 2KW generator operation.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7BA-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-3014-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform 2KW generator servicing procedures.

Requirement. N/A

Performance Standard. With supervision, perform 2KW generator servicing procedures.

Prerequisites. Complete level 2000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4001-8304 [G] N/A N/A B N/A A N/A Times: 1

Task. Maintain cleanliness of the PGCS/PGDT.

Requirement. N/A

Performance Standard. Without supervision, maintain cleanliness of the PGCS/PGDT.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4002-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform GCS/PGDT power up/power down procedures.

Requirement. N/A

Performance Standard. Without supervision, perform PGCS/PGDT power up/power down procedures.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4003-830405 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove RF box.

Requirement. N/A

NAVMC 4790.02

15 Jun 12

Performance Standard. Without supervision, remove RF box.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4004-830405 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install RF box.

Requirement. N/A

Performance Standard. Without supervision, install RF box.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4005-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT tripod.

Requirement. N/A

Performance Standard. Without supervision, remove PGDT tripod.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4006-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT tripod.

Requirement. N/A

Performance Standard. Without supervision, install PGDT tripod.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4007-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove PGDT primary antenna.

Requirement. N/A

Performance Standard. Without supervision, remove PGDT primary antenna.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4008-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT primary antenna.

Requirement. N/A

Performance Standard. Without supervision, install PGDT primary antenna.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4009-830402 [P] N/A N/A B N/A A N/A Times: 1

NAVMC 4790.02

15 Jun 12

Task. Remove PGDT secondary antenna.

Requirement. N/A

Performance Standard. Without supervision, remove PGDT secondary antenna.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4010-830402 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install PGDT secondary antenna.

Requirement. N/A

Performance Standard. Without supervision, install PGDT secondary antenna.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4011-8304 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove UPS.

Requirement. N/A

Performance Standard. Without supervision, remove UPS.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4012-8304 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install UPS.

Requirement. N/A

Performance Standard. Without supervision, install UPS.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4013-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform 2KW generator operation.

Requirement. N/A

Performance Standard. Without supervision, perform 2KW generator operation.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7BA-NFM-000

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-4014-8304 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform 2KW generator servicing procedures.

Requirement. N/A

Performance Standard. Without supervision, perform 2KW generator servicing procedures.

Prerequisites. Complete level 3000 PGCS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

15 Jun 12

Exams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

PGCS-6001-8304	[N/A]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-------	-----	-----	---	-----	---	-----	----------

Task. Complete level 100 through 4000 PGCS tasks .Requirement. N/APerformance Standard. Complete level 1000 through 4000 PGCS tasks.Prerequisites. Complete level 4000 PGCS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

2.1.12 TACTICAL AUTOMATIC LANDING SYSTEM (TALS). The TALS System (TALS) tasks provide the required knowledge to perform special/conditional inspections on the TALS system as it pertains to the individual's MOS. Upon completion of the TALS system tasks, level 2000-4000, the individual shall be certified as TALS SSP. An individual that is TALS SSP Certified has the ability to act as the supervising authority of a task.

Table 2-12. Maint System "Tactical Automatic Landing System" (TALS)

Maintenance Systems					
Tactical Automatic Landing System (TALS)					
INDOC	BASIC	INTERMEDIATE	ADVANCE	MGMT	QDL
N/A	2001-2012	3001-3012	4001-4012	N/A	6001

NOTE

For task header description see Appendix A

TALS-2001-8307	[E]	N/A	N/A	B	N/A	A	N/A	Times: 1
----------------	-----	-----	-----	---	-----	---	-----	----------

Task. Perform TALS power up/power down procedures.Requirement. N/APerformance Standard. With supervision, perform TALS power up/power down procedures.Prerequisites. Complete level 1000 TALS tasks.External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2002-83070101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove tracking control unit (TCU).

Requirement. N/A

Performance Standard. With supervision, remove tracking control unit (TCU).

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2003-83070101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install tracking control unit (TCU).

Requirement. N/A

Performance Standard. With supervision, install tracking control unit (TCU).

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2004-83070102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove interrogator.

Requirement. N/A

Performance Standard. With supervision, remove interrogator.

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2005-83070102 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install interrogator.

Requirement. N/A

Performance Standard. With supervision, install interrogator.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2006-83070102 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove antenna radome.

Requirement. N/A

Performance Standard. With supervision, remove antenna radome.

Prerequisites.. Complete level 1000 TALS tasks.

External Syllabus Support.. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2007-8307010203 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install antenna radome.

Requirement. N/A

Performance Standard. With supervision, install antenna radome.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2008-8307010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove pedestal.

Requirement. N/A

Performance Standard. With supervision, remove pedestal.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2009-8307010201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install pedestal.

Requirement. N/A

Performance Standard. With supervision, install pedestal.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2010-8307010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove base leveling assembly.

NAVMC 4790.02

15 Jun 12

Requirement. N/A

Performance Standard. With supervision, remove base leveling assembly.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2011-8307010201 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install base leveling assembly.

Requirement. N/A

Performance Standard. With supervision, install base leveling assembly.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-2012-8307 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform TALS fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform TALS fault isolation.

Prerequisites. Complete level 1000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3001-8307 [E] N/A N/A B N/A A N/A Times: 1

Task. Perform TALS power up/power down procedures.

Requirement. N/A

Performance Standard. With supervision, perform TALS power up/power down procedures.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3002-83070101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove tracking control unit (TCU).

Requirement. N/A

Performance Standard. With supervision, remove tracking control unit (TCU).

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3003-83070101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install tracking control unit (TCU).

Requirement. N/A

Performance Standard. With supervision, install tracking control unit (TCU).

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

15 Jun 12

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARTALS-3004-8307010202 [P] N/A N/A B N/A A N/A Times: 1Task. Remove interrogator.Requirement. N/APerformance Standard. With supervision, remove interrogator.Prerequisites. Complete level 2000 TALS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARTALS-3005-83070102 [Q] N/A N/A B N/A A N/A Times: 1Task. Install interrogator.Requirement. N/APerformance Standard. With supervision, install interrogator.Prerequisites. Complete level 2000 TALS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/AExams. N/AT&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QARTALS-3006-8307010203 [P] N/A N/A B N/A A N/A Times: 1Task. Remove antenna radome.Requirement. N/APerformance Standard. With supervision, remove antenna radome.Prerequisites. Complete level 2000 TALS tasks.External Syllabus Support. N/AAcademics: N/AReferences. A1-RQ7B-IETMLectures. N/AIMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3007-8307010203 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install antenna radome.

Requirement. N/A

Performance Standard. With supervision, install antenna radome.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3008-8307010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove pedestal.

Requirement. N/A

Performance Standard. With supervision, remove pedestal.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3009-830701020101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install pedestal.

Requirement. N/A

Performance Standard. With supervision, install pedestal.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

NAVMC 4790.02

15 Jun 12

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3010-8307010201 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove base leveling assembly.

Requirement. N/A

Performance Standard. With supervision, remove base leveling assembly.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3011-830701020101[Q] N/A N/A B N/A A N/A Times: 1

Task. Install base leveling assembly.

Requirement. N/A

Performance Standard. With supervision, install base leveling assembly.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-3012-8307 [Y] N/A N/A B N/A A N/A Times: 1

Task. Perform TALS fault isolation.

Requirement. N/A

Performance Standard. With supervision, perform TALS fault isolation.

Prerequisites. Complete level 2000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-4001-8307 [E] N/A N/A B N/A A N/A Times: 1

Task. TALS power up/power down procedures.

Requirement. N/A

Performance Standard. Without supervision, perform TALS power up/power down procedures.

Prerequisites. Complete level 3000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-4002-83070101 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove tracking control unit (TCU).

Requirement. N/A

Performance Standard. Without supervision, remove tracking control unit (TCU).

Prerequisites. Complete level 3000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-4003-83070101 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install tracking control unit (TCU).

Requirement. N/A

Performance Standard. Without supervision, install tracking control unit (TCU).

NAVMC 4790.02

15 Jun 12

Prerequisites. Complete level 3000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-4004-8307010202 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove interrogator.

Requirement. N/A

Performance Standard. Without supervision, remove interrogator.

Prerequisites. Complete level 3000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-4005-8307010202 [Q] N/A N/A B N/A A N/A Times: 1

Task. Install interrogator.

Requirement. N/A

Performance Standard. Without supervision, install interrogator.

Prerequisites. Complete level 3000 TALS tasks.

External Syllabus Support. N/A

Academics: N/A

References. A1-RQ7B-IETM

Lectures. N/A

IMIs. N/A

Exams. N/A

T&R Task Sign-Off Authority. 6314 MOS CDI, 6314 MOS CDQAR, 6314 MOS QAR

TALS-4006-8307010203 [P] N/A N/A B N/A A N/A Times: 1

Task. Remove antenna radome.

Requirement. N/A